

**Internship Report**  
**On**  
**MANAGEMENT OF GARMENT QUALITY**  
**CONTROL SYSTEM IN FIAT FASHION LTD.**

**Submitted by**

Md. Shahidul Islam

ID: 123-14-896

Faculty of Business and Economics

Daffodil International University

**Supervised By**

Sumon Mozumder

Assistant Professor

Daffodil International University



Daffodil International University

Dhaka, Bangladesh.

August 2019

**Internship Report**  
**On**  
**MANAGEMENT OF GARMENT QUALITY**  
**CONTROL SYSTEM IN FIAT FASHION LTD.**

**Submitted by**

Md. Shahidul Islam

ID: 123-14-896

Faculty of Business and Economics

Daffodil International University

**Supervised By**

SumonMozumder

Assistant Professor

Daffodil International University



Daffodil International University

Dhaka, Bangladesh.

December-2019

December 23, 2019

To  
SumonMozumder  
Assistant Professor  
Department of Business Administration,  
Daffodil International University

**Subject: Submission of Internship Report.**

Dear Sir,

I am pleased to declare that I have completed my Internship Program in the Fiat Fashion Ltd. “**Management of Garment Quality Control System in Fiat Fashion Ltd.**” for your kind evaluation. To prepare this report, I have given my best efforts that would enhance the project report.

This report attempts to describe my observations, learning during the study this course. I made sincere efforts to continue the survey related materials, documents and operational systems and examine relevant records for preparation of the Internship paper as comprehensive and informative as possible within the time allowed for me. Due to various reason there may be some mistakes for which I beg your apology.

I would be glad if you accept the term paper and also requesting to consider limitations with a soft view that had made due to my limitations and oblige thereby.

Yours faithfully,

Md. ShahidulIslam  
ID: 123-14-896  
Program: MBA (Executive)  
Apparel Management and Merchandising  
Department of Business Administration.  
Daffodil International University


## LETTER OF APPROVAL

This internship report prepared by **Md. Shahidul Islam**, bearing **Id:123-14-896** is approved for partial Fulfillment of the requirement for the Degree of MASTERS IN BUSINESS ADMINISTRATION. The student has completed his three months internship program in of “**Management of Garment Quality Control System in Fiat Fashion Ltd.**” under my supervision. During the internship period I found him sincere, hardworking and enthusiastic.

SUMON MOZUMDER

ASSISTANT PROFESSOR

DAFFODIL INTERNATIONAL UNIVERSITY

A handwritten signature in black ink, followed by the date "13.12.19". The signature is stylized and appears to be "Sumon Mozumder". The date is written in a simple, clear font.

## **PREFACE**

The Internship report is made on the topic “Investigation on **Management of Garment Quality Control System in Fiat Fashion Ltd.**” Now the business is more competitive and challenging in the fashion world. So we try to understand where need to develop the quality control system for a factory for PULL & BEAR, LEFTIES and LPP buyer. Different buyers ask quality in different standard, some buyers demand very rich quality, some buyer demand reasonable quality as international standard. Here also an important things that all buyer ask quality not in a same way and same points. Some buyer like to get their product inspection by third party like ITS,SGS, BV etc. Some buyer likes to get their product by own inspector and some buyer like to judge their product by trading house. Here a common things that all buyer has segregated the defects count on critical, major & minor. This type of report helps the students to acquire particular knowledge about an international buyer. They are developing quality control system as following the buyer requirements and trying to find out all weakness of quality.

In the time of making report some important information of the textile industry like yarn count selection, yarn test, fabrics inspection, weight measurement, shrinkage test, shade segregation, Accessories check, pattern check, marker check, pre-production meeting, Size set sample check, spreading quality assurance, cutting quality assurance, General instruction on product, 100% In line process check, Sewing final check, hourly audit with measurement, finishing 100% check, Button Pulls check, Broken needle check, Accessories compliance, Pre final inspection, Ready for final inspection, Final inspection and Shipment.

If buyer instruction is wash effect on knit garments or garment dye then need more awareness about yarn selection to shipment or completing the order execution. Yarn count selection is very important for specific GSM and shrinkage, otherwise fabrics quality will not be in control.

During this period got help from the Management of Fiat Fashion Ltd. Fabrics department, cutting department, sewing department, finishing department specially quality department, GPQ and the inspector of PULL & BEAR, LEFTIES, LPP buyer.

## **ABSTRACT**

This study mention to find the quality effect on the order of all type of Garments such as T-Shirt, Polo-shirt, Trousers, Tank top and hoody Jacket which consumed by existing buyer like PULL& BEAR, LEFTIES and LPP inFiat Fashion Ltd. This study investigate by using three point like critical, major & minor defects on the Garments from inspection report which has done after final inspection. The main objective is to find quality control process of garments in this factory. This survey has been exposed the quality level of each buyer and make a report basis on accepted quality level (AQL). Every buyer has been provided their quality requirement and accepted level of their standardization. The report has been provided name of buyer, name of products, fabric GSM(Gram per square meter), size ratio, AQL requirement(total accepted quantity & total rejected quantity), quantity of Garments, sample size, name of defects(critical, major & minor), inspection results(pass or fail) reference number ( order number or style name). The total number of inspection reports 24 on 3 buyers and each buyer of 8 reports in this factory. Every report has been shown final result like pass or fail depend on Accepted quality level (AQL). Finally, the report is shown over all factory standard on quality level. I hope this investigation will be helpful to evaluate the quality standard to entire a new buyer in this factory.

# CONTENTS

## Contents:Page No.

01. Letter of Transmittal-----	i
02. Letter of approval-----	ii
03. Preface-----	iii
04. Abstract-----	iv
05. List of Tables /Charts-----	vi
06. List of Figures-----	vii
07. List of Abbreviations -----	viii
08. Introduction-----	1
09. Background of the study -----	3
10. Scope of the study-----	5
11. Problem Statement/Objective of the study-----	6
12. Methodology-----	7
13. Limitations of the Study-----	9
14. Discussion, Analyses and Findings-----	10
15. Recommendations-----	26
16. Reference-----	27
17. Conclusion-----	28

## List of Tables

<b>Table No.</b>	<b>Title of the Tables</b>	<b>Page No.</b>
Table No.7.1	The table is showing basic information on eight inspection reports for PULL & BEAR buyer	12
Table No.7.2	The table is showing basic information on eight inspection reports for LPP buyer	15
Table No. 7.3	The table is showing basic information on eight inspection reports for LEFTIES buyer	20



## List of Figures

<b>Figure No.</b>	<b>Title of the Figures</b>	<b>Page no.</b>
Figure no. 7.1	Number of FI reports where mention critical, major & minor defects for PULL & BEAR.	13
Figure no. 7.2	Pie diagram representing the percentage (%) of critical, Major & minor defects for PULL & BEAR buyer.	14
Figure no. 7.3	Number of FI reports where mention critical, major & minor defects for LPP	18
Figure no. 7.4	Pie diagram representing the percentage (%) of critical, Major& minor defects for LPP buyer.	19
Figure no. 7.5	Number of FI reports where mention critical, major & minor defects for LEFTIES.	22
Figure no. 7.6	Pie diagram representing the percentage (%) of critical, Major& minor defects for LEFTIES buyer.	23
Figure no. 7.7	Bar diagram on final investigation results for specific buyer of fiat fashion Ltd.	24
Figure no. 7.8	Pie diagram representing the percentage (%) of final results for specific buyer.	25

## **List of Abbreviations**

GSM- Gram per Square meter

RMG- Ready Made garments

GSP- Generalized System of preference

AQL - Accepted Quality Level

FI- Final Inspection

FY - Financial year

BGMEA – Bangladesh Garment manufacturers and exporters association

GDP – Gross domestic product

RQS – requirement for the quality system

GPQ – Guideline of production quality

# 1. Introduction

**Quality control system** in terms of garment manufacturing, pre-sales and posts sales service, delivery, pricing, etc are essential for any garment manufacturer, trader or exporter. Certain quality related problems, should never be over looked. The consumers want to get high quality products in low price. The products should reach the consumers with right quality depends on the cost. Quality management is the aspect of the overall management function that determines and implements the quality policy. Quality assurance covers all the process within a company that contributes to the production of quality products. The inspection is carried out by representatives of the current production and the result record on control chart.

RMG at Bangladesh, A great achievement that high profiled buyers are working in Bangladesh and coming huge of dollars every year. Worldwide most reputed buyers like to get product from Bangladesh. But history of the beginning time of garments industry when it was starting at Bangladesh then it was very much difficult to make qualified products.

Like other 3rd world countries Bangladesh is a developing country. Her economic development depends firstly on agriculture and secondly on industry. Although Bangladesh is not developed in industry, it has been enriched in Garment industries in the recent past years. In the field of Industrialization garment industry is a promising step. It has given the opportunity of employment to millions of unemployed, specially innumerable uneducated women of the country. It is making significant contribution in the field of our export income.

Once the cloth of Bangladesh achieved worldwide fame specially muslin and jamdani cloth or our country was used as the luxurious garments of the royal figures in Europe and other countries. Garment Industry Large-scale production of readymade garments (RMG) in organized factories is a relatively new phenomenon in Bangladesh.

Since the late 1970s, the RMG industry started developing in Bangladesh primarily as an export-oriented industry although; the domestic market for RMG has been increasing fast due to increase in personal disposable income and change in life style. The sector rapidly attained high importance in terms of employment, foreign exchange earnings and its contribution to GDP.

Most importantly, the growth of RMG sector produced a group of entrepreneurs who have created a strong private sector. Of these entrepreneurs, a sizeable number is female. A woman entrepreneur established one of the oldest export-oriented garment factories, the Baishakhi Garment in 1977. Many women hold top executive positions in RMG industry. The hundred percent export-oriented RMG industry experienced phenomenal growth during the last 15 or so years. In 1978, there were only 9 export-oriented garment manufacturing units, which generated export earnings of hardly one million dollar. Some of these units were very small and produced garments for both domestic and export markets. Four such small and old units were Reaz Garments, Paris Garments, Jewel Garments and Baishakhi Garments.

Reaz Garments, the pioneer, was established in 1960 as a small tailoring outfit, named Reaz Store in DHAKA. It served only domestic markets for about 15 years. In 1973 it changed its name to M/s Reaz Garments Ltd. and expanded its operations into export market by selling 10,000 pieces of men's shirts worth French Franc 13 million to a Paris-based firm in 1978. It was the first direct exporter of garments from Bangladesh. Desh Garments Ltd, the first non-equity joint-venture in the garment industry was established in 1979. Desh had technical and marketing collaboration with Daewoo Corporation of South Korea. It was also the first hundred percent export-oriented company. It had about 120 operators including 3 women trained in South Korea, and with these trained workers it started its production in early 1980. Another South Korean Firm, Young-ones Corporation formed the first equity joint-venture garment factory with a Bangladeshi firm, Trexim Ltd. in 1980.

Till the end of 1982, there were only 47 garment manufacturing units. The breakthrough occurred in 1984-85, when the number of garment factories increased to 587. The number of RMG factories shot up to around 2,900 in 1999. Bangladesh is now one of the 12 largest apparel exporters of the world, the sixth largest supplier in the US market and the fifth largest supplier of T-shirts in the EU market. The industry has grown during the 1990s roughly at the rate of 22%.

At present there are about 5000 garment industries in the country and 75 percent of them are in Dhaka. The rest are in Chittagong and Gazipur. These Industries have employed fifty lacks of people and 85 percent of them are illiterate rural women. About 76 percent of our export earning comes from this sector.

## 2. Background of Study

The textile sector was first established in the 60th decade of 19th century. We have learned that the first shipment is Mercury shirt to the European market in 1965-66, which was produced from Karachi. In the latter, 9 exporting industries were available in 1977-78. The three largest industries in that time were Riaz Garments, Jewel Garments and Paris Garments. Among those, Riaz Garments was the most famous and oldest industry in that time. When I have started to continue the survey “Preference of Consumers on Purchasing Branded RMG Products” it was found that lot of segment effect on this survey. For this reason I have tried to find out which segment effect mostly to continue the survey “Preference of Consumers on Purchasing Branded RMG Products. Here the survey was continued based on fourteen segments[1]

This survey is continued on different RMG product in different cities. This survey is continued mainly two cities, Dhaka and Gazipur and few other cities like N. Gonj, Munsigonj, Norsingdi etc. Survey is continued based on 200 person .If the survey was continued another city of Bangladesh then survey result could be changed. The apparel industry, employer of 40 million workers, mostly rural women, contributed 83.49% to Bangladesh’s total exports of \$36.66 billion to date. Bangladesh’s export earnings from the apparel sector registered an 8.76% growth reaching \$30.61 billion in FY18, thanks to safety improvements[2].

According to Export Promotion Bureau (EPB) data released on Wednesday, Bangladesh’s export earnings from the RMG sector stood at \$30.61 billion, posting 8.76% growth in the last fiscal year. The figure is 1.51% higher than the target of \$30.16 million for FY18. In FY17, Bangladesh’s export earnings registered a 0.2% growth to \$28.15 billion, the lowest in the last one and a half decade. Of the total amount, Knitwear products earned \$15.18 billion, which is 10.40% higher than the \$13.76 in the same period a year ago. Woven products earned \$15.42 billion, up by 7.18%, compared to \$14.39 billion a year ago. Meanwhile, Bangladesh’s overall export earnings rose about 5.8% to \$36.66 billion, which was \$34.65 billion in Fy17. Talking to Dhaka Tribune about export performance, manufacturers gave credit to safety improvements in the apparel industry, restoring buyer confidence to place more orders here. On the other hand, economists say this growth is not up to mark, considering the industry’s potential. “In the last couple of years, global retailers were slow to place orders due to ongoing safety inspections in

the apparel sector. But in the last fiscal, they changed their mind set as the inspection has almost come to an end showing significant progress,” Exporters Association of Bangladesh (EAB) president, Abdus Salam Murshedy, told the Dhaka Tribune. As a result, export earnings have seen a rise, but it could be more, said Salam. “The present export growth is better compared to the previous year. But there is more space to grow in terms of export earnings,” Bangladesh Garment Manufacturers and Exporters Association (BGMEA) president, MdSiddiqurRahman, told the Dhaka Tribune. According to the World Trade Statistical Review 2017, Bangladesh’s global market share in clothing was 6.4% in 2016 [3].

“Showing a growth over the previous year’s export earnings does not mean a good picture of the export sector. Export contribution to Gross Domestic Product (GDP) is showing a continuous downward trend [ **Self collection**]

Bangladesh needs a strong double digit growth in export earnings to meet the expenses of development projects. Slower growth in export performance would widen the balance of payments gap, said the economist. With the present growth rate, Bangladesh would not be able to reach the target of \$60 billion export earnings by 2021, said Ahsan. In attaining the desired target, the government has to bring reforms to bonded warehouse facilities, export facilities given to entrepreneurs. Infrastructure development is also a must, he added. Assuming the present competition in the RMG sector we need to develop quality in each and point. To stand in the fashion world no way without developing quality. Demand of the time need to achieve better quality to create customer attraction [4].

### **3. SCOPE OF THE STUDY**

We faced some problems, but below mentioned facility have found during the survey.

- This survey is continued based on Fiat Fashion Ltd. at the requirement for quality system (RQS) and guideline for production quality (GPQ) department.
- Invitation of inspection or inspection offer mail send to the buyer and from their confirmation to this manufacturer for final inspection FI / FRI.
- Inspector makes inspection and explain in details about quality based on critical major and minor.
- This survey result is found based on 3 buyer's final inspection reports.
- This survey result is found based on 24 final inspection reports.
- Every report is facilitated on the products between buyer and Fiat Fashion Ltd.

## 4. OBJECTIVES OF THE STUDY

In general, research objectives describe what we expect to achieve with this project. A statement of research objectives can serve to guide the activities of research. Here the Objective of the study is classified into two categories as below.

**Board objectives** of this research work are given below-

To investigation Garment Quality Control Process in Fiat Fashion Ltd.

**Specific objectives** of this research work are given below-

- ✦ To find out how many types of quality of RMG products.
- ✦ To find out the critical, major and minor defects on the basic types of defect.
- ✦ To justify a quality standard of a factory.
- ✦ To find out the quality preference based on product's styling and associated buyers.



## 5 Methodology

I have collected the secondary data from 24 inspection reports which are done by Quality Control (QC). Normally I have collected data after inspection in a same day or day after. All information are mention in a report like name of buyer, name of products, fabric GSM(Gram per square meter), size ratio, AQL requirement(total accepted quantity & total rejected quantity), quantity of Garments, sample size, name of defects(critical, major & minor), inspection results(pass or fail) reference number ( order number or style name) etc. But I had main focus on quality as I making a report like this. After finishing the inspection I checked inspection report and note down AQL basis. Every day I went inspection room of all brand like PULL & BEAR, LPP & LEFTIES.

Following factors were considered during the data collection process-

- ✚ Buyers
- ✚ Product's styling
- ✚ Type of fabrics used in making garment
- ✚ Product's size ratio
- ✚ Accepted Quality Level (AQL)
- ✚ Type of Garments defects quantity compare with Accepted Quality Level (AQL)

Here mentioned some quality defects in cutting section:

When finished fabrics received at store department it checked each and every roll avoiding any kind of rejection. Fabrics whole, low gsm, shade not okay, uneven color, crease mark, needle mark, thick thin, color crease fabrics are not accepted. After receiving okay fabrics from store it lay down at cutting table and start cutting as following approved pattern. Cutting part checked each & every peace's to send printing department if it needed. Printed parts are ready for sewing following the instruction as approved PP sample or if any comments. In this all process factory has to take approval from buyer or their agent at bd.

Here mentioned some quality defects at sewing section:

Open seams, wrong stitching techniques, non-matching threads, missing stitches, improper creasing of the garment, improper thread tension etc. are some of the sewing defects.

Broken or defective buttons, snaps, stitches, different shades within the same garment, dropped stitches, exposed notches, fabric defects, holes, faulty zippers, loose or hanging sewing threads, misaligned buttons and holes, missing buttons, needle cuts, pulled or loose yarn, stains, unfinished buttonhole, short zippers, inappropriate trimmings etc. all can lead to the end of a brand name even before its establishment. During the sewing “In process quality control” is done by the line QC’s through .For critical operations 100% process inspection are carried out. The following parameters are also checked in sewing process –a) Machine check. b) Tensioncheck.c) SPI checksd) Needle check.e) Cleanness.d) Table inspection.f) Inspection before wash. Washing sectiona) Garments handlingb) Wash standard.c) After wash thoroughly inspection.

Quality control of finishing sections: Following inspection/audit is done to attain AQL (1.5/2.5/4.0etc).a) Process inspection: Garments are checked process wise in the finishing section to identify defects and pass only the passed garments. Two hourly audit: Every after two-hours audit is done on finishing lot to attain AQL the required.Days final audit: At the end of the day accumulated lot of finished garments are statistically audited to attain required AQL.

“A set of co-ordinated activities to direct and control an organization in order to continually improve the effectiveness and efficiency of its performance.” Each Quality management systems (TQM, ISO etc) and its elements (Statistical process control, (SPC), Kaizen, Advance product quality planning and control (APQP), have a distinctive applicability. It is necessary that the approach selected suits current and future needs of the organization. SPC works towards bringing process under the influence of common causes alone by identifying & eliminating assignable causes. APQP focuses mainly on new product development/project execution. ISO 9000 currently includes three quality standards (ISO 9000:2005, ISO 9001:2000, and ISO 9004:2000). ISO 9001:2000 presents ISO’s new quality management system requirements, while ISO 9000:2005 and ISO 9004:2000 Present ISO’s new quality management system guidelines. All of these are process standards & not product standards and are developed by quality experts from around the world for use by companies that either want to implement their own in-house quality systems or to ensure that suppliers have appropriate quality systems in place.

## **6. Limitations**

To collect current inspection report and to make a total report according to brand to brand facing understanding problem with the quality department. Although all the brand has almost same requirement. But I have faced some limitation here are mention below:

- The survey is limited in only 24 inspection reports.
- Report has done only three (3) buyer if have more than three (3).
- There are lot of RMG factory in Bangladesh but we surveyed only one factory
- Due to time limitation I couldn't found more reports with more specifications.


## 7. Discussions, Analyses and Findings

**Table - 7.1 : The table are showing basic information on four inspection reports for PULL & BEAR buyer :**

S L N O. ..	Name of Buyer	Name of product	Fabric construction	Fabric WEIGHT	Size Ratio	AQL Requirement	AQL		Qty of Garments	Sample Size	Name of Defects	Type of Garments Defects			Inspection Result	Order Number
							Total Accepted qty	Total Rejected qty				Critical	Major	Minor		
							1	PULL & BEAR				MEN'S R-NECK T-SHIRT	60% CTTN 40% POLYE S/J	140		
											Print Up down	0	2	0		
											SewingProblem	0	0	8		
											Spot	0	3	0		
											Twisting	0	1	3		
											Sleeve Up down	0	2	0		
											Uncut Thread	0	0	5		
											Broken Stitch	0	1	0		
<b>TOTAL</b>													<b>12</b>	<b>21</b>		
2	PULL & BEAR	MEN'S R-NECK T-SHIRT	60% CTTN 40% POLYE S/J	140	S,M,L,XL & XXL	2.5	14	14	45,000	500	Sewing Problem	0	4	4	Pass	56412-W
											Uncut Thread	0	0	4		
											Unfastens seam	0	2	0		
											Open Seam	0	1	0		
											Broken stitch	0	1	0		
											Cutting Sticker	0	0	1		
											Shading	0	4	0		
											Poor Tension	0	4	0		
											Fabrics Defects	0	1	0		
											Iron Problem	0	0	5		
<b>TOTAL</b>													<b>17</b>	<b>14</b>		
3	PULL & BEAR	MEN'S V-NECK T-SHIRT	60% POLY 40% CTTN S/J	140	S,M,L,XL & XXL	2.5	13	14	30,032	315	Bad shape	0	0	3	Pass	56448-W
											Broken Stitch	0	3	0		
											Oil Spot	0	1	0		
											Hole	0	1	0		
											Poor Tension	0	2	0		
											Skip Stitch	0	1	0		
											Shading	0	1	0		
											Dirty Spot	0	3	0		
											Fabrics Fault	0	1	0		
											Sewing	0	0	8		


											Problem					
<b>TOTAL</b>											Iron Problem	0	0	4		
<b>TOTAL</b>												13	15			
4	PULL & BEAR	MEN'S V-NECK T-SHIRT	100% CTTN S/J	160	S,M,L,XL & XXL	2.5	06	07	3,000	125	Dirty Spot	0	2	2	Pass	76999-W
											Oil Spot	0	1	0		
											Sewing Problem	0	0	4		
											Up Down	0	0	3		
											Sleeve up down	0	1	0		
											Twisting	0	0	3		
											Shine mark	0	0	2		
											Uncut thread	0	0	1		
											Bad shape	0	2	0		
<b>TOTAL</b>												06	15			
5	PULL & BEAR	MEN'S V-NECK T-SHIRT	60% POLY 40% CTTN S/J	150	S,M,L,XL & XXL	2.5	14	10	8,000	200	Dirty Spot	0	3	4	Pass	56602-W
											Print Problem	0	0	4		
											V shape odd	0	3	0		
											V Tuck Problem	0	3	0		
											Twisting	0	0	4		
											Skip Stitch	0	2	0		
											Broken stitch	0	1	0		
											Bottom shape uneven	0	2	0		
											Sewing Problem	0	0	4		
											Uncut thread	0	0	2		
Cutting sticker	0	0	1													
<b>TOTAL</b>												14	19			
6	PULL & BEAR	MEN'S R-NECK T-SHIRT	60% POLY 40% CTTN S/J	160	S,M,L,XL & XXL	2.5	14	32	18,912	315	Insects	0	4	0	Fail	621256-W
											Fabric hole	0	5	0		
											Dirty Spot	0	7	6		
											Skip Stitch	0	2	0		
											Broken Stitch	0	5	0		
											Unfasten seam	0	3	0		
											Uncut thread	0	0	1		
											Fabrics Defec	0	1	1		
											Iron problem	0	0	2		
											Asymmetric bottom	0	3	2		
											Join Stitch	0	0	1		
											Oil spot	0	1	0		
Open Label	0	1	0													
<b>TOTAL</b>												32	13			

7	PULL & BEAR	MEN'S V-NECK T-SHIRT	100% CTTN S/J	160	S,M,L,XL & XXL	2.5	14	18	60,000	500	V-Tuck problem	0	3	1	Fail	56392-W											
											Broken Stitch	0	4	0													
											Fabric Hole	0	2	0													
											Puckering	0	3	0													
											Dirt spot	0	3	2													
											Print Problem	0	1	0													
											Uncut Thread	0	0	4													
											Sewing problem	0	0	6													
											Skip stitch	0	1	0													
											Hiking	0	1	0													
											TOTAL											18	13				
											8	PULL & BEAR	MEN'S R-NECK T-SHIRT	100% CTTN S/J			160	S,M,L,XL & XXL	2.5	10	07	20,000	315	Shading	0	2	0
Sewing Problem	0	0	4																								
Bad neck Shape	0	2	0																								
Uncut Thread	0	0	3																								
Twisting	0	1	2																								
Sleeve up down	0	1	0																								
Broken stitch	0	1	0																								
Iron problem	0	0	3																								
TOTAL											07	12															



**Figure-7.1: Number of FI reports where mention critical, major & minor defects for PULL& BEAR.**

Here randomly take of eight inspection reports on eight different products like Men's s/s t-shirt, for buyer of PULL & BEAR. According to PULL & BEAR requirement inspection has done on 2.5 AQL (Accepted Quality Label). Inspector inspect the order on quantity base like first order quantity 20,000 pcs check sample size 315 pcs here separate three category defects products like critical, major&minor. Each category mentions maximum quantity of defective sample. Above the bar chart we found critical defect quantity is 0, major 12 and minor 21 pcs. So here inspection result is pass. According to for 2<sup>nd</sup> order critical quantity is 0, major 17 and minor 14 as inspection result is pass. For 3<sup>rd</sup> order critical quantity 0, major 13 and minor 15 where inspection result is pass. For the 4<sup>th</sup> order found critical 0, major 06 and minor 15 where inspection result is also pass. For the 5<sup>th</sup> order found critical 0, major 14 and minor 19 where inspection result is also pass. For the 6<sup>th</sup> order found critical 0, major 28 and minor 13 where inspection result is also fail. For the 7<sup>th</sup> order found critical 0, major 18 and minor 13 where inspection result is also Fail. For the 8<sup>th</sup> order found critical 0, major 07 and minor 12 where inspection result is also pass



**Figure-7.2: Pie diagram representing the percentage (%) of critical, major & minor defects for PULL & BEAR buyer.**

Here we can see total defects percentage for PULL & BEAR brand in this factory like 49% Major defects 51% Minor defects and 0% Critical defects from above table with random 4 inspection report.




## 7. Discussions, Analyses and Findings

Table - 7.2 : The table are showing basic information on four inspection reports for LPP buyer.

S L N O ..	Name of Buyer	Name of product	Fabric construction	Fabric WEIGHT	Size Ratio	AQL Requirement	AQL		Qty of Garments	Sample Size	Name of Defects	Type of Garments Defects			Inspection Result	Order Number		
							Total Accepted qty	Total Rejected qty				Critical	Major	Minor				
							1	LPP				MEN'S R-NECK T-SHIRT	100% CTN S/J	140			S,M,L,XL & XXL	2.5
											Fabric Hole	0	4	0				
											Broken Stitch	0	1	0				
											Print Problem	0	0	4				
											Open seam	0	1	0				
											Asymmetric bottom	0	2	3				
											Poor Tension	0	1	0				
TOTAL													11	07				
2	LPP	LADIES 3/4 S T-SHIRT	100% CTN S/J	140	S,M,L,XL & XXL	2.5	07	09	2016	80	Dirt Spot	0	2	3	Pass	6111165/66		
											Unfastens Seam	0	1	0				
											Uncut Thread	0	0	5				
											Open seam	0	2	0				
											Twisting	0	1	4				
											Broken stitch	0	1	0				
											Sewing Problem	0	0	5				
											Up down	0	0	2				
TOTAL													09	16				
3	LPP	LADIES T-SHIRT	60% POLY 40% CTTN S/J	140	S,M,L,XL & XXL	2.5	11	10	6240	125	Poor tension	0	1	0	Pass	632755		
											Pleat	0	1	0				
											Pocket Slanted	0	3	0				
											Sewing Problem	0	0	8				
											Uncut thread	0	0	4				
											Sleeve open up down	0	1	0				
											Skip Stitch	0	1	0				
											Dirty Spot	0	2	0				
											Bad Finish	0	1	3				
											Measurement	0	1	0				


TOTAL											Problem			11	15		
4	LPP	MEN'S S/S T-SHIRT	100% CTN S/J	140	S,M,L,XL & XXL	2.5	10	08	3,222	125	Bad finish shape	0	3	0	Pass	609011-13	
											Cut to tuck	0	1	0			
											Measurement Problem	0	2	0			
											Bad Neck shape	0	2	0			
											Sewing Problem	0	0	8			
											Print Problem	0	0	3			
TOTAL													08	11			
5	LPP	MEN'S S/S T-SHIRT	100% CTN S/J	160	S,M,L,XL & XXL	2.5	14	16	15,264	200	Sewing Problem	0	0	7	Pass	613121-22	
											Oil spot	0	4	0			
											Dirty Spot	0	2	3			
											Bad shape	0	0	3			
											Iron Problem	0	0	6			
											Uneven bottom	0	1	4			
											Fabric hole	0	4	0			
											Unfasten seam	0	3	0			
											Broken stitch	0	2	0			
TOTAL													16	23			
6	LPP	MEN'S POLO SHIRT	100% CTTN S/J	170	S,M,L,XL & XXL	2.5	05	07	1680	80	Sewing problem	0	0	3	Pass	622414	
											Uncut thraed	0	0	3			
											Iron problem	0	0	3			
											Fabric Hole	0	1	0			
											Uneven bottom shape	0	1	0			
											Placket problem	0	2	0			
											Dirt spot	0	1	0			
											Button Problem	0	2	0			
											Bad shape	0	0	2			
TOTAL													07	11			
7	LPP	MEN'S POLO SHIRT	100% CTTN S/J	180	S,M,L,XL & XXL	2.5	05	08	960	50	Sewing problem	0	0	3	Fail	618430	
											Placket Uneven	0	2	0			
											Loose Tuck	0	1	0			
											Dirt spot	0	1	0			
											Down stitch	0	1	0			
											Neck shape Problem	0	0	0			
											Uncut thread	0	0	7			
TOTAL													08	10			

8	LPP	MEN'S R-NECK T-SHIRT	100% CTTN S/J	160	S,M,L ,XL & XXL	2.5	14	26	1100	200	Print Spot	0	1	0	Fail	619490		
											Bottom up down	0	1	4				
											Broken stitch	0	3	0				
											Oil spot	0	4	0				
											Sleeve up down	0	2	0				
											Dirt spot	0	8	0				
											Sewing problem	0	0	9				
											Pleat	0	1	0				
											Bad Shape	0	0	0				
											Fabric hole	0	2	0				
											Poor Neck	0	0	4				
											Tuck problem	0	1	0				
											Needle mark	0	0	1				
											Open Seam	0	2	0				
											Insects	0	1	0				
TOTAL													26	18				



**Figure-7.3: Number of FI reports where mention critical, major & minor defects for LPP.**

Here randomly take of eight inspection reports on eight different products like Men’s s/s t-shirt, Polo Shirt for buyer of LPP. According to LPP requirement inspection has done on 2.5 AQL (Accepted Quality Label). Inspector inspect the order on quantity base like first order quantity 29,40 pcs check sample size 80 pcs here separate three category defects products like critical, major&minor. Each category mentions maximum quantity of defective sample. Above the bar chart we found critical defect quantity is 0, major 11 and minor 07 pcs. So here inspection result is fail. According to for 2<sup>nd</sup> order critical quantity is 0, major 09 and minor 16 as inspection result is pass. For 3<sup>rd</sup> order critical quantity 0, major 11 and minor 15 where inspection result is pass. And for the 4<sup>th</sup> order found critical 0, major 08 and minor 11 where inspection result is also pass. For 5<sup>th</sup> order critical quantity 0, major 16 and minor 23 so inspection result is pass. For 6<sup>th</sup> order critical quantity 0, major 07 and minor 11 inspections result is also pass. For 7<sup>th</sup> order critical quantity 0, major 08 and minor 10 so inspections result is fail. For 8<sup>th</sup> order critical quantity 0, major 26 and minor 18 inspections result is also fail.



**Figure-7.4: Pie diagram representing the percentage (%) of critical, major & minor defects for LPP buyer.**

Here we can see total defects percentage for LPP brand in this factory like 46% Major defects 54% Minor defects and 0% Critical defects from above table with random 8 inspection report.


## 7. Discussions, Analyses and Findings

**Table - 7.3 : The table are showing basic information on Eight inspection reports for Lefties Buyer:**

S L N O	Name of Buyer	Name of product	Fabric construction	Fabric WEIGHT	Size Ratio	AQL Requirement	AQL		Qty of Garments	Sample Size	Name of Defects	Type of Garments Defects			Inspection Result	Order Number		
							Total Accepted qty	Total Rejected qty				Critical	Major	Minor				
							1	Lefties				Girls Tops	100% SLUB CTN S/J	140			2/3,3/4,4/5, 5/6,7/8,9/10, 11/12	2.5
											Tuck Missing	0	3	0				
											Needle cut	0	1	0				
											Fabric whole	0	1	0				
											Oil Spot	0	0	4				
											Uncut Thread	0	0	7				
											Fly yarn	0	0	1				
											Dirty spot	0	1	0				
											Chalk mark	0	0	2				
											Loose thread	0	0	3				
TOTAL													8	17				
2	Lefties	LADIES S/S T-SHIRT	100% CTN S/J	140	S,M,L,XL	2.5	14	12	20,800	315	Reject	0	3	0	Pass	41569-K		
											Broken stitch	0	3	0				
											Dirty spot	0	1	2				
											Uncut thread	0	2	4				
											Twisting	0	0	2				
											Bottom uneven	0	0	4				
											Armhole Irregular	0	1	2				
											Print spot	0	2	5				
TOTAL													12	19				
3	Lefties	MEN'S PRINTED T-SHIRT	100% CTTN S/J	150	S,M,L,XL & XXL	2.5	14	10	28,660	315	Ratio Mistake	0	1	0	Pass	64009-K		
											Rejection	0	3	0				
											Broken stitch	0	2	0				
											Twisting	0	1	2				
											Part shading	0	1	0				
											Rib shading	0	0	1				
											Dirty spot	0	0	3				
											Oil mark	0	0	2				

															Foreign yarn	0	0	1		
															Care Label Damage	0	1	0		
															Poor neck shape	0	0	5		
															Bottom uneven	0	0	1		
															Print uneven	0	1	0		
TOTAL																10	15			
4	Lefties	GIRLS L/SLV T-SHIRT	95% CTN 5% 2X2 RIB	190	2/3,3/4,4/5, 5/6,7/8,9/10,11/12	2.5	10	8	11,950	315				Pleat	0	1	0			
														Stripe up down	0	2	3			
														Poor neck shape	0	2	4			
														Sleeve joint sharing	0	1	3			
														Dirty Spot	0	0	2			
														Cut at side seam	0	1	0			
														Main Label Slanted	0	0	2			
														Twisting	0	1	0			
														Cross point up down	0	0	3			
TOTAL																8	17			
5	Lefties	MEN'S S/SAOP T-SHIRT	100% CTN S/J	150	S,M,L,XL & XXL	2.5	10	8	3600	200				Broken stitch	0	1	0			
														Print spot	0	1	2			
														Oil spot	0	1	2			
														Shading	0	1	1			
														Twisting	0	2	2			
														Dirty spot	0	0	2			
														Broken print	0	2	1			
TOTAL																8	10			
6	Lefties	MEN'S PRINTED T-SHIRT	100% CTTN S/J	160	S,M,L,XL & XXL	2.5	21	14	35,563	500				Rejection	0	1	0			
														Care Label Damage	0	3	0			
														W/O price sticker	0	1	0			
														Broken Stitch	0	2	0			
														Main Label open	0	2	0			
														Rib shading	0	2	4			
														Broken Print	0	1	3			
														Twisting	0	1	2			
														Print slanted	0	1	0			
														Part shading	0	0	3			
														Oil Mark	0	0	2			
														Dirty Spot	0	0	3			
														Cross point up down	0	0	4			
TOTAL																14	21			
7	Lefties	GIRLS TOP	100% CTTN S/J	150	2/3,3/4,4/5, 5/6,7/8,9/10, 11/12	2.5	10	6	15,600	315				Skip stitch	0	2	0			
														Hole	0	2	0			
														Broken size sticker	0	1	0			
														Twisting	0	0	2			
														Dirty spot	0	0	1			

													Uncut thread	0	0	4		
													Pleat	0	1	0		
TOTAL													6	7				
8	Lefties	BABY'S TOP	100% CTTN S/J	140	2/3,3/4,4/5, 5/6,7/8,9/10, 11/12	2.5	10	4	3599	200		Fabric rejection	0	1	0	Pass	19052-K	
											Broken stitch	0	1	0				
											Back rise slanted	0	1	0				
											Dirty Spot	0	1	0				
											Uncut thread	0	0	7				
TOTAL													4	7				




**Figure-7.5: Number of FI reports where mention critical, major & minor defects for LEFTIES.**

Here randomly take of eight inspection reports on eight different products like Men's s/s t-shirt, Girls Tops, and Girls Skirts for buyer of LEFTIES. According to LEFTIES requirement inspection has done on 2.5 AQL (Accepted Quality Label). Inspector inspect the order on quantity base like first order quantity 20,185 pcs check sample size 315 pcs here separate three



category defects products like critical, major&minor. Each category mentions maximum quantity of defective sample. Above the bar chart we found critical defect quantity is 0, major 8 and minor 17 pcs. So here inspection result is passing. According to for 2<sup>nd</sup> order critical quantity is 0, major 12 and minor 19 as inspection result is pass. For 3<sup>rd</sup> order critical quantity 0, major 10 and minor 15 where inspection result is passing. And for the 4th order found critical 0, major 8 and minor17 where inspection result is also pass. For the 5th order found critical 0, major 8 and minor10 where inspection result is also pass. For the 6th order found critical 0, major 14 and minor21 where inspection result is also pass. For the 7th order found critical 0, major 6 and minor 7 where inspection result is also pass. And for the 8th order found critical 0, major 4 and minor 7 where inspection result is also pass.




**Figure-7.6: Pie diagram representing the percentage (%) of critical, major & minor defects for LEFTIES buyer.**

Here we can see total defects percentage for LEFTIES brand in this factory like 38% Major defects 62% Minor defects and 0% Critical defects from above table with random 8 inspection report.


**Table-7.4: The table is showing over all summery on inspection report’s results for Specific buyer.**

Buyer Name	Pass	Fail	Total number of inspection	Percentage (%) Buyer Acceptance
PULL & BEAR	5	3	8	62.5%
LPP	5	3	8	62.5%
LEFTIES	8	0	8	100%



**Figure-7.7: Bar diagram on final results for specific buyer of Fiat Fashion Ltd.**

Here are showing pass and fail number with the buyer name in the same row. For the PULL & BEAR buyer the number of pass report is 5 and fail 3 of FI. For the LPP buyer the number of pass report is 5 and fail 3 of FI. For the LEFTIES buyer the number of pass report is 8 and fail 0 of FI.



**Figure-7.8: Pie diagram representing the percentage (%) of final results for specific buyer.**

Here we can see total inspection pass percentage 75% and fail percentage 25% for specific buyer from above pie diagram of Fiat fashion Ltd. So we can say factory quality aren't so good or not under control and they have to improve more specific point.

## 8. Recommendation

Following recommendations are very important to consider for further study:

- The study is restricted to 24 inspection reports, but analysis of more reports might have influence on the current results.
- This work considered only three (03) buyers, but need to include other buyers to improve the results.
- One RMG factory was selected to conduct the research work whereas for more factories may have different findings. So, it will be better to compare results among various factories.
- There was time limitation in this work which may be improved with involving more time.

## 9. References

- [1] [https://www.academia.edu/27123751/Quality\\_Control\\_Mechanism\\_in\\_RMG\\_sector\\_of\\_Bangladesh](https://www.academia.edu/27123751/Quality_Control_Mechanism_in_RMG_sector_of_Bangladesh)
- [2] <https://www.dhakatribune.com/business/2018/07/05/rmg-exports-saw-8-76-growth-last-fiscal-year>
- [3] <https://www.coursehero.com/file/p6v212g/The-ready-made-garments-RMG-industry-in-Bangladesh-has-experienced-an/>
- [4] Self-observation.
- [5] <https://www.worldbank.org/en/news/press-release/2019/10/10/world-bank-bangladesh-economy-continues-robust-growth-with-rising-exports-and-remittances>

## 10. Conclusion

This survey is carried out on 24 Inspection reports of different RMG products under different buyers in Fiat fashion Ltd. This study is ended with the following imperative findings:

- For PULL & BEAR buyer the acceptance percentage is 62.5% on four (8) Final Inspection (FI). Where quality level is not so good for this buyer.
- For LPP buyer the acceptance percentage is 62.5% on four (8) Final Inspection (FI). Where quality level is not so good for this buyer.
- For LEFTIES buyer the acceptance percentage is 100% on four (8) Final Inspection (FI). Where quality level is good for this buyer.

Over all, we can see total inspection pass percentage 75% and fail percentage 25% for specific buyer from above pie diagram of Fiat fashion Ltd. So, we can say factory quality are satisfactory or under control but they need to improve more specific point.

Factory Name: FIAT FASHION  
 Customer: POLLWE BANK  
 Dept: MEN'S WNT  
 Production in Factory: 56395-A  
 Order no: 824  
 Style: Basic V Neck  
 Description: 3/4 S/W V Neck  
 Ex-fac Date: 15.04.2017  
 Packing way: Solid/Pcs  
 Ship status: SEA MDR  
 Sample in Hand: YCS  
 poly bag in house: YCS  
 Carton in house: YCS  
 Sewing Lab in house: YCS  
 Sticker in house: YCS  
 Loading status: 100%  
 DATE: 19-04-2017  
 Order Qty: 20,000 Pcs  
 Ship Qty: 20,575 Pcs  
 carton Qty: 194 Chs  
 Insp Ratio: ADL-2.5  
 Loading Discrepancy: Yes  
 Per carton: Seafork List

Sample Provided By:  Buyer  Supplier  No Sample  
 AQL STANDARD - ANSI/ASQC Z1.4-2003 LEVEL II (AQL-:  1.5  2.5  4.0)

Color: CHIN FAN - 824  
 CHIN CLAT - 824  
 ACCESSORIES:  Hang tag,  Price sticker,  Washing instruction,  Label,  Spare button,  zipper,  Blotom,  Care LBL,  Iron LBL,  Ping  
 PACKING:  Shopping mark,  Size of Carton/Meas,  way of Pack,  Way of folding

COLOR	SOLID/PCS		ASSORT/PEL-PACK	
	Carton no	Inspection/Pcs	Carton No	Inspection/Pcs
CHIN FAN - 824	C/KD - 78, 84, 32, 46, 15, 16, 98, 102			56395 Pcs
CHIN CLAT - 824				

Presentation/Make up Fault's	Major	Minor	Comment's	Status
Bad Neck	III	III		
Point Up Down	II			
Staining Problem	✓	III		
Spot	III			
TE shirt	✓	III		
Slit Up Down	II			
Unit Loose Thread		III	AVL Loose Thread Inside of Body	
Bad Neck Strain	I			
Point Problem				

RESUME OF INSPECTION: INVOICE NO - Fiat/As/23/17

	Accept	Problem	Accept	Problem	
Fabric Quality	OK		Decoration	OK	C-Critical
Color Dyeing	OK		Measurement		B-Big
Appearance	OK		Hangtag/Labels	OK	S-Small
Workmanship		3	Packing		
Terminology	OK		Other's		

PO CHG NOT FOUND INSPECTION TIME S/B CHANGE

SIGNATURE: [Signature]  
 Starrex Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp Date: [Signature]

SIGNATURE: [Signature]  
 Starrex Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp date: [Signature]

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL 2.5  AQL 4.0  
 Inspected Qty: 12  
 ACCEPTED  
 R. REPACK (See per pack report)

Inspection Qty	<u>315 Pcs</u>
Number of Major Faults	<u>12</u>
% of Major Faults	<u>3.80 / 6.66</u>

INSPECTION RESULT  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: Unit Lot - Pcs. (1+1+2+2+1+1) As per PO sheet wise  
824 - Order Dfp. 145 Pcs But from 143 Pcs 2 Pcs Sm  
 Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Supplier/Factory Representative: [Signature]  
 Factory Seal: [Seal]

Factory Name: Flor Fashion  Pre-Production Inspection  In-Line Inspection  Final Inspection  Re-Inspection

Customer: Pollu, Bank  
 Dept: Men's knit  
 Production in Factory:  
 Order no: 56012-N  
 Style: 9242/553  
 Description: 2/5W Knit  
 Ex-fac Date:  
 Packing way:

Ship status: SEA WARE  
 Sample in Hand: YES  
 poly bag in house: YES  
 Carton in house: YES  
 Sewing Lbl in house: YES  
 Sticker in house: YES  
 Loading status: 100%

DATE: 28-04-2011  
 Order Qty: 45000 Pcs.  
 Ship Qty: 46424 Pcs.  
 carton Qty: 427 Ctns  
 Insp. Ratio: ADL-2.5  
 Loading Discrepancy: YES  
 Per carton: See pack list

Solid/Pcs: 46424 Assort/Pre Pack: \_\_\_\_\_  
 Sample Provided By:  Buyer  Supplier  Factory  No Sample

AQL STANDARD - ANSI/ASQC Z1.4-2003 LEVEL II (AQL -  1.5  2.5  4.0)

Color	REQ Gsm	Result
WHITE - 250		
Grey - 712		
Black - 800		

**ACCESSORIES**  
 Main Label  Hang tag  Price Sticker  Washing Instruction  washing Symbol  spare button  zipper  Button  Care LBL/size LBL/Flag  
**PACKING**  
 Shipping mark  Size of Carton/Meas  way of Pack  Way of folding Goods  Other

**INSPECTED CARTON:**

COLOR	Carton no	SOLID/PCS Inspection/Pcs	ASSORT/PRE-PACK Carton No	Insp/Pcs
WHITE - 250				
Grey - 712				500 Pcs.
Black - 800				

**INSPECTION'S DETAILS:**

Presentation/Make up Fault's	Major	Minor	Comment's	Status
SEAMING Problem				
UNCUT Thread				
Undershirt SEAM		✓	ARM HOLE / SLV AREA	
OPEN SEAM		✓	SHOULDER AREA	
BROKEN STITCH		✓	NECK CHAIN STITCH	
COLLING STICKER		1		
SHOULDER		✓	NECK SHIRT + BODY FABRIC	
ROCK TENSION		✓	BACK PART OF BODY FABRIC	
FABRIC WOOD DEFECT		✓		
3-TON Problem				

**RESUME OF INSPECTION:**

	Accept	Problem	Accept	Problem	
Fabric Quality	OK		OK		C-Critical
Color/Dyeing	OK			B	B-Big
Appearance	OK		OK		S-Small
Workmanship	OK		OK		
Trimings	OK				

SIGNATURE  
 Startex Clothing Company  
 Inspector Name: \_\_\_\_\_  
 Designation: \_\_\_\_\_  
 ID No: \_\_\_\_\_  
 Insp Date: \_\_\_\_\_  
 Start Time: \_\_\_\_\_ Am/Pm  
 End Time: \_\_\_\_\_ Pm

SIGNATURE  
 Startex Clothing Company  
 Inspector Name: \_\_\_\_\_  
 Designation: \_\_\_\_\_  
 ID No: \_\_\_\_\_  
 Insp date: \_\_\_\_\_

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL-2.5  AQL 4.0  
 Inspected Qty.  
 ACCEPTED  
 R: REPACK (See pre pack report)

Inspection Qty	500 Pcs.
Number of Major Faults	12 14
% of Major Faults	2.4% 2.8%

**INSPECTION RESULT**

PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: WHITE-250, Grey-712 BODY FABRIC COLOR SHADE 2 TYPE FOUND

Vendor/Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Supplier/Factory representative

Factory Seal



STARTEX clothing company  
 House-365, Road-06, Baridhara DOHS, Dhaka-1206, Tel-88 02-8412073, 88 02-8470977  
 www.startex-clothing.com

Factory Name: Flat/PS/101A  Pre-Production Inspection  In-Line Inspection  Final Inspection  Re-Inspection

Customer: PULL & BEAR Ship status: SPAMODE DATE: 04-05-2017  
 Dept: MEN'S W/IT Sample in Hand: YES Order Qty: 30,032 Pcs  
 Production in Factory: 56,486 W poly bag in house: YES Ship Qty: 30,428 Pcs  
 Order no: 5240/500 Carton in house: YES carton Qty: 285 Chj  
 Style: 5240/500 Sewing Lbl In house: YES Insp Ratio: ADL-2.5  
 Description: V Neck T-shirt Sticker in house: YES Loading Discrepancy: YES  
 Ex-fac Date: 04-05-2017 Loading status: 100% Per carton: See Pack list  
 Packing way: Solid Pcs 30478 Pcs

Sample Provided By:  Buyer  Supplier Papana  Factory  No Sample

Assort/Pre Pack: \_\_\_\_\_

AQL STANDARD - ANSI/ASQC Z1 4-2003 LEVEL-II (AQL -  1.5  2.5  4.0)

Color	REQ Qty	Result
White-250		
Black-800		

ACCESSORIES:  Main Label OK  Hang tag OK  Price Sticker OK  Washing Instruction OK  washing Symbol OK  spare button OK  zipper OK  Button OK  Care Lbl/size Lbl/Flag

PACKING:  Shipping mark OK  Size of Carton/Meas OK  way of Pack OK  Way of folding OK

INSPECTED CARTON:

COLOR	Carton no	SOLID/PCS Inspection/Pcs	ASSORT/PRE-PACK Carton No	Insp/Pcs
White-250	C/NO - Black-52, 45, 140, 143, 105, 128, 133, 40,			
Black-800	White-03, 141, 83, 21, 12, 17, 90, 81, 86, 142, 126, 101			515 Pcs

58x38x40 CM

INSPECTION'S DETAILS:

Presentation/Make up Fault's	Major	Minor	Comment's	Status
Bad Staff				
Broken stitch				
Oil spot				
Hole				
Shorten Sew				
Slip stitch				
Stare				
Dirty				
Label with defect				
Printed problem				
Iron problem				

13, 15, 14/15

RESUME OF INSPECTION: INVOICE NO - Flat/PS/80/12 (Black) Flat/PS/105/17 (White)

	Accept	Problem	Accept	Problem	
Fabric Quality	OK		OK	B	C-Critical
Color/Dyeing		Stare			B-Big
Appearance	OK		OK		S-Small
Workmanship	OK		OK		
Trimmings	OK		OK		

SIGNATURE: [Signature] Inspection Result - QUALITY:  AQL 2.5  AQL 4.0

Startex Clothing Company Inspector Name: [Signature] Pre Pack:  AQL-2.5  AQL 4.0

Designation: [Signature] ID No: 0012 Insp Date: 04-05-17 Insp date: \_\_\_\_\_

Start Time: \_\_\_\_\_ Am/Pm End Time: \_\_\_\_\_ Pm

Inspection Qty	315 Pcs
Number of Major Faults	13, 15
% of Major Faults	4.12%, 4.76%

INSPECTION RESULT:  PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: White-250 color, Aismode, Black-800 color, SPAMODE, Black color 2 type, fabric, stare found inspection time.

Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's

Supplier/Factory Representative: \_\_\_\_\_ Factory Seal: [Signature] 04-05-17

STARTEX clothing company  
House-365, Road-06, Baridhara DOHS, Dhaka-1206. Tel-88 02-8412073, 88 02-8470977

www.startex-clothing.com

Factory Name: Flat Position

Customer: Billaboard  
Dept: Mens Wear  
Production in: Bangladesh  
Order no: 1619 W.  
Style: 9231/204  
Description: Logo Asia  
Ex-fac Date: 15-05-2017  
Packing way: Solid Pcs 3104 Pcs

Ship status: Sea Mode  
Sample in Hand: YES  
poly bag in house: YES  
Carton in house: YES  
Sewing Lbl in house: YES  
Sticker in house: YES  
Loading status: 100%

DATE: 15-05-2017  
Order Qty: 3000 Pcs  
Ship Qty: 3104 Pcs  
carton Qty: 30 Ctns  
Insp Ratio: AQL-2.5  
Loading Discrepancy: 100  
Per carton: Sea pack List

Assort/Pre Pack: Null

Sample Provided By:  Buyer  Supplier  Factory  No Sample

AQL STANDARD - ANSI/ASQC Z1 4-2003 LEVEL-II (AQL -  1.5  2.5  4.0)

Color: White Navy Blue  
Knew: Black  
Black: Citrusal

ACCESSORIES  
 Main Label  Hang tag  Price sticker  Washing Instruction  Washing Symbol  Spare button  zipper  Button  Care LBL/size LBL/Flag LBL

PACKING  
 Shipping mark  Size of Carton/Meas  way of Pack  Way of folding Goods  Others

INSPECTED CARTON: 58x38x40 CM

COLOR	Carton no	SOLID/PCS Inspection/Pcs	ASSORT/PRE-PACK Carton No	Insp/Pcs
WHITE Navy Knew. Pk.	C/NO-	15, 18, 23, 24, 30, 26, 05, 02, 09, 06,		125 Pcs
Black CITRUSAL		16, 19		

INSPECTION'S DETAILS:

Presentation/Make up Fault's	Major	Minor	Comment's	Status
Dusty spot				
DL SPOT	I			
SCARCE Problem				
UP DOWN				
TAJISHIR	I			
SHIRT A MARK				
WASH/LOOSE THREAD		I		
POO SHAP/ODD				

(16) (15) (2/18)

RESUME OF INSPECTION: INVOICE NO - Flat/PB/86/17

Accept	Problem	Accept	Problem	C-Critical
OK		OK	B	B-Big
OK		OK		S-Small
OK		OK		
OK		OK		
OK				

SIGNATURE: Startex Clothing Company  
Inspector Name: [Signature]  
Designation: [Signature]  
ID No: [Signature]  
Insp date: [Signature]

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
Pre Pack  
 AQL-2.5  AQL 4.0  
Inspected Qty: [Signature]  
 ACCEPTED  
 R. REPACK (See pre pack report)

Inspection Qty	125	
Number of Major Faults	06	15
% of Major Faults	4.8%	12%

INSPECTION RESULT  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: PO SHORT WISE UNIT LOT 1 FOLLOW THIS PACK RATIO.

Vendor or Supplier's manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Supplier's Representative: [Signature]  
Factory Seal: [Signature]

Factory Name: FIAT FASHION

Customer: Allice Beal  
 Dept: MEN'S LWIT  
 Production in Factory: 55802-A  
 Order no: 55802-A  
 Style: 5240/501  
 Description: 3/4 sleeve  
 Ex-fac Date: 15-05-17  
 Packing way: Solid Pcs

Ship status: SEA MODE  
 Sample in Hand: YES  
 poly bag in house: YES  
 Carton in house: YES  
 Sewing 1:1 in house: YES  
 Sticker in house: YES  
 Loading status: 100%

DATE: 15-05-2017  
 Order Qty: 30,000 Pcs  
 Ship Qty: 3415 Pcs  
 carton Qty: 328 CB  
 Insp Ratio: ADL-2.5  
 Loading Discrepancy: NO  
 Per carton: See pre pack

Sample Provided By:  Buyer  Supplier  Factory  No Sample

AQL STANDARD - ANSI/AQC Z14-2003 LEVEL II (AQL:  1.5  2.5  4.0)

Color	REQ Qm	Result
Navy Blue	401	
CHINTON	824	
CHIN CLOR	827	

- ACCESSORIES**
- Main Label ✓  Hang tag ✓  Price Sticker ✓  Washing Instruction ✓  washing Symbol ✓
  - spare button ✓  zipper  Button  Case LBL/size LBL/Wtag LBL ✓
- PACKING**
- Shipping mark ✓  Size of Carton/Meas ✓  way of Pack ✓  Way of folding Goods ✓  Others

INSPECTED CARTON:

COLOR	Carton no	SOLID/PCS Inspection/Pcs	ASSORT/PRE-PACK Carton No	Insp/Pcs
Navy Blue	C/N/D			
CHINTON				
CHIN CLOR				315 Pcs

INSPECTION'S DETAILS:

Presentation/Make up Fault's	Major	Minor	Comment's	Status
Spot / Dirty				
Print Problem				
V Shape Odd				
Waist Problem				
Waist Stitch				
Waist Stitch				
Bottom Slitch				
Bottom Slitch/Even				
SEWING Problem				
Unset / Loose Thread				
Cutting Slitches				

RESUME OF INSPECTION: Invoice no - Fiat/As/88/17

	Accept	Problem	Accept	Problem	
Fabric Quality	OK		OK		C-Critical
Color/Dyeing	OK			3	B-Big
Appearance	OK		OK		S-Small
Workmanship	OK		OK		
Packings	OK		OK		

STARTEX  
 Signature  
 Inspector Name  
 Designation  
 ID No  
 Insp Date

SIGNATURE  
 Startex Clothing Company  
 Inspector Name  
 Designation  
 ID No  
 Insp Date

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL-2.5  AQL-4.0  
 Inspected Qty  
 ACCEPTED  
 R-REPACK (See pre pack report)

Inspection Qty	315
Number of Major Faults	14
% of Major Faults	4.44% / 6.03%

INSPECTION RESULT  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: Poly pack folding boxes shows some faults

Vendor or Supplier/Manufacturing are hold fully responsibility for any defects and claims from the buyer's

Supplier Representative

Factory Seal

Buyer Name: Flat location  
 Customer: LPO - House  
 Dept: Ladies knit  
 Production in Factory: 601355  
 Order No: 150-010 RY-3US  
 Description: LADIES T-shirt  
 Ex-fac Date: 15-05-2015  
 Packing way: Solid Pcs  
 Ship status: SEAFOOD  
 Sample in Hand: YES  
 poly bag in house: YES  
 Carton in house: YES  
 Sewing L&M in house: YES  
 Stocker in house: YES  
 Loading status: 100%  
 DATE: 15-05-2015  
 Order Qty: 1000 Pcs  
 Ship Qty: 1000 Pcs  
 carton Qty: 1000 Pcs  
 Insp Ratio: ASL - 4.0  
 Loading Discrepancy: YES  
 Per carton: 100 Pcs

Sample Provided By:  Buyer  Supplier  No Sample  
 Account/Pre Pack:  No Sample  
 AGE STANDARD - ANSEASQC 27 & 2009 LEVEL-11  
 Color: CREAM, Navy, Turquoise, Black  
 Accessories:  Minus Label  Hang tag  Price sticker  Washing instruction  Sewing Symbols  Great Detail  Paper  Blank  Care Label  Poly Bag  
 Packing:  Staggered  Size of Carton/Minus  Way of Pack  Way of Loading  
 Grade: OK Other: OK

INSPECTED CARTON	COLOR	Carton no	SIZE/PCS	INSPECTION/PCS	Carton No	ASMT/PCS	PREL/PACK
	CRIM 99% BM	C/N/O - 10	53, 66, 20, 155, 123, 80, 129, 185, 60, 102				
	10% RIX 99% BM	45, 27, 38, 57, 109, 150, 175, 159, 162, 92, 136, 90					200 Pcs

INSPECTION'S DETAILS	Major	Minor	Comment's	Status
Presentation/Make up Fault's				
Label			Inside of poly bag	
Fabric Hand				
Dirty spot / Hair mark				
Zip Stitch				
Button Stitch				
Washmark seam				
Pinch				
Fabric defect				
Roller mark / Bow mark				
Asymetric / Bottom seam				
Join Stitch				
Oil spot				
Open Label				

RESUME OF INSPECTION	Accept	Problem	Accept	Problem	
Fabric Quality	OK		OK		C-Critical
Color Dyeing		S		B	B-Big
Appearance	OK			A, B	S-Small
Workmanship		B			
Findings	OK		OK	Hand tag Barcode visible	

SIGNATURE  
 StarTEX Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp Date: [Signature]  
 Start Time: 09:30 AM  
 End Time: 02:00 PM

SIGNATURE  
 StarTEX Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp date: [Signature]

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL 2.5  AQL 4.0  
 Inspected Qty:  
 ACCEPTED  
 R: REPACK (See pre pack report)

Inspection Qty	200 Pcs
Number of Major Faults	02
% of Major Faults	1% / 6.5%

INSPECTION RESULT  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comments of Inspection: Bottom Puchering + weavy Bottom slw Lower part show Asymmetric slw Bottom also. C/W Empty space 4cm.

Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's.  
 Supplier Factory: [Signature] Factory Seal

factory Name: Fiat Fashion (1)  
 Customer: Pullu Bear DATE: 22-04-2017  
 Dept: MAN'S KNIT Ship status: SCAMPOR Order Qty: 60,000 Pcs  
 Production in Factory: 20,603 Pcs Ship Qty: 20,603 Pcs  
 Order no: 56392-W carton Qty: 198 Chj  
 Style: 5236/514 Insp Ratio: AD1-2.5  
 Description: 45WV Neck Loading Discrepancy: Yes  
 Ex-fac Date: \_\_\_\_\_ Per carton: See full list  
 Packing way: \_\_\_\_\_ Assort/Pre Pack: \_\_\_\_\_

Sample Provided By:  Buyer  Supplier  Factory  No Sample  
 AQL STANDARD - ANSI/ASQC Z1 4-2003 LEVEL II (AQL -  1.5  2.5  4.0)

Color: YELLOW-300  
 REQ Gsm: \_\_\_\_\_ Result: \_\_\_\_\_  
 ACCESSORIES:  Main Label  Hang tag  Price Sticker  Washing Instruction  washing Symbol  spare button  zipper  Button  Care LBL/size LBL/Flag  
 PACKING:  Shipping mark  Size of Carton/Meas  way of Pack  Way of folding Goods  Others \_\_\_\_\_

COLOR	SOLID/PCS		ASSORT/PRE-PACK	
	Carton no	Inspection/Pcs	Carton No	Insp/Pcs
<u>Yellow-300</u>	<u>C/100</u>	<u>132 172 07, 53, 72, 91, 108, 190,</u> <u>144, 36, 192 193.</u>		<u>315 Pcs</u>

INSPECTION'S DETAILS:		Major	Minor	Comment's	Status
✓	Tuck Problem Neck		I	NOT IN CENTER. TUCK	
✓	Broken SHIR.			NECK T SWIRL	
✓	Fabric Hole			ARMHOLE AREA	
✓	Dirty spot/Print spot			BACK NECK PRINT CROPPED	
✓	Print Problem	I	/ AVL	BOTTOM HEM AREA	
✓	Unweft/Loose Thread	I		BACK FRONT NOT UPDOWN	
✓	Sewing Problem	I			
✓	Skip Shir.	I			
✓	Updown/Hiking	I			

RESUME OF INSPECTION: (18) (13)

	Accept	Problem	Accept	Problem	
Fabric Quality	OK		OK	B	C-Critical
Color/Dyeing	OK		OK	B	B-Big
Appearance	OK		OK	B	S-Small
Workmanship		B			
Trainings	OK				

Other's: holding Board shown from pack

SIGNATURE: \_\_\_\_\_  
 Startex Clothing Company  
 Inspector Name: Da (R) W.  
 Designation: \_\_\_\_\_  
 ID No: 0012  
 Insp Date: 22-04-2017

SIGNATURE: \_\_\_\_\_  
 Startex Clothing Company  
 Inspector Name: \_\_\_\_\_  
 Designation: \_\_\_\_\_  
 ID No: \_\_\_\_\_  
 Insp date: \_\_\_\_\_

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL 2.5  AQL 4.0  
 Inspected Qty: 06  
 ACCEPTED  
 R-REPACK (See pre pack report)

Inspection Qty	<u>315 Pcs</u>
Number of Major Faults	<u>18 13</u>
% of Major Faults	

INSPECTION RESULT  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: 56392-W Order no. Part shipment. Mixed chj 192, 193 size dry NOT attached inspection time.

Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's.  
 Supplier's Representative: \_\_\_\_\_  
 Factory Seal: \_\_\_\_\_

Pre-Production Inspection /  In-Line Inspection /  Final Inspection /  Re-Inspection

Buyer Name: Fiat Fashion DATE: 23-04-2017  
 Brand: Police Bear Order Qty: 20,000 Pcs  
MAN'S WOLF Ship status: SEAFOOD Ship Qty: 10,259 Pcs  
 Production in Factory: 56459-2/2 poly bag in house: Yes  
 Carton no: 5240/501 Carton in house: Yes  
 Description: MAN'S WOLF Sewing Lbl in house: Yes  
 Issue Date: 23-04-2017 Sticker in house: Yes  
 Loading status: Yes Per carton: See pack list

Assort/Pre Pack:  No Sample  
 Sample Provided By:  Buyer  Supplier Part DTP  Factory (AQL -  1.5  2.5  4.0)

**AQL STANDARD - ANSI/ASQC Z1 4-2003 LEVEL II**

Color	REQ Gsm	Result
<u>NAVY BLUE</u>	<u>401</u>	

Main Label OK  Hang tag OK  Price Sticker OK  Washing Instruction OK  washing  
 Symbol OK  spare button OK  zipper OK  Button OK  Care LBL/size LBL/Flag

Shipping mark OK  Size of Carton/Meas OK  way of Pack OK  Way of folding  
 Goods OK  Others

INSPECTED CARTON:	SOLID/PCS		ASSORT/PRE-PACK	
	Color	Carton no	Carton No	Insp/Pcs
<u>NAVY BLUE</u>	<u>59</u>	<u>C/N0 - 95, 97, 42, 09, 20, 02, 38, 85, 74</u>		<u>200 Pcs</u>

INSPECTION'S DETAILS:	Major	Minor	Comment's	Status
<u>Presentation/Make up Fault's</u>	<u>II</u>	<u>III</u>		
<u>SHADING</u>		<u>III</u>		
<u>SEWING PROBLEMS</u>	<u>II</u>	<u>III</u>		
<u>BAD NECK STITCH</u>		<u>III</u>		
<u>INCORRECT THREAD</u>	<u>I</u>	<u>II</u>		
<u>WASTING</u>				
<u>SLU UPDOWN</u>	<u>I</u>			
<u>BACK STITCH</u>		<u>III</u>		
<u>IRON PROBLEM</u>				

RESUME OF INSPECTION:

	Accept	Problem	Accept	Problem	C-Critical	B-Big	S-Small
Fabric Quality	<u>OK</u>		Decoration	<u>OK</u>			
Color/Dyeing	<u>OK</u>		Measurement		<u>3</u>		
Appearance	<u>OK</u>		Hangtag/Labels	<u>OK</u>			
Workmanship	<u>OK</u>		Packing	<u>OK</u>			
Trimnings	<u>OK</u>		Other's				

SIGNATURE: [Signature]  
 Startex Clothing Company  
 Inspector Name: [Name]  
 Designation: [Designation]  
 ID No: [ID]  
 Insp date: 23-04-2017

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL-2.5  AQL 4.0  
 Inspected Qty  
 ACCEPTED  
 R: REPACK (See pre pack re

Inspection Qty	Number of Major Faults	% of Major Faults
<u>200 Pcs</u>	<u>07</u>	<u>3.5%</u>

PASS  FAILED  RE CHECKED  WAITING FOR APPROV.

General Comment's of:

Factory Name: Barishal DOH  Pre-Production Inspection  In-Line Inspection  Final Inspection  Re-Inspection

Customer: Reserved/LPP  
 Dept: MEN'S UNIT  
 Production to: Factory  
 Order no: 208990-91  
 Style: MU-398  
 Description: MEN'S SHIRT  
 Ex-fac Date: 02-04-2013  
 Packing way: Solid/Pcs

Ship status: Air Mail  
 Sample in Hand: YES  
 poly bag in house: YES  
 Carton in house: YES  
 Sewing Lbl in house: YES  
 Sticker in house: YES  
 Loading status: 100%

DATE: 02-04-2013  
 Order Qty: 252 + 2688  
 Ship Qty: 252 + 2520  
 carton Qty: 05 + 50  
 Insp Ratio: AQL-2.5  
 Loading Discrepancy: Yes  
 Per carton: See pack list

Sample Provided By:  Buyer  Supplier Russia + Poland  Factory  No Sample

AQL STANDARD - ANSEASQCZI 4-2003 LEVEL-II (AQL -  1.5  2.5  4.0)

Color	REQ Qty	Result
Black 99%		

ACCESSORIES  
 Main Label OK  Hang tag OK  Price Sticker OK  Washing Instruction OK  washing Symbol OK  spare button  zipper  Blotter  Care LBL/size LBL/Flag LBL OK

PACKING  
 Shipping mark OK  Size of Carton/Meas OK  way of Pack OK  Way of folding Goods OK  Others

INSPECTED CARTON:

COLOR	SOLID/PCS		ASSORT/PRE-PACK	
	Carton no	Inspection/Pcs	Carton No	Inspection/Pcs
Black 99%	C/NO - Russia - 02			80
	Poland - 2A, 19, 12, 10, 25			

INSPECTION'S DETAILS:

Presentation/Make up Fault's	Major	Minor	Comment's	Status
Printed Mark	11	04		
Hole / TACKLE REJECT	1111			
Bottom SHIRT	1		Print Horizontal, AOP Koush	
Print problem		1111		
Open Seam	1			
ASYMMETRIC BOTTOM SHIRT	11	111	BOTTOM HEM AREA	
POIN POSITION	1			

NOTE: AOP Point Horizontal Pouch Backside type color not matching 2 type sample found.

RESUME OF INSPECTION:

	Accept	Problem	5	6	Accept	Problem	
Fabric Quality	OK				OK		C-Critical
Color/Dyeing		B				B	B-Big
Appearance	OK				OK		S-Small
Workmanship		B			OK		
Trainings	OK				OK		

SIGNATURE  
 Startex Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp Date: 02-04-2013

SIGNATURE  
 Startex Clothing Company  
 Inspector Name:  
 Designation:  
 ID No:  
 Insp date:

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL-2.5  AQL 4.0  
 Inspected Qty  
 ACCEPTED  
 R- REPACK (See pre pack report)

Inspection Qty	80 Pcs
Number of Major Faults	11
% of Major Faults	13.75%

INSPECTION RESULT

PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: Poland Part Assort Pack Poi- 2 chn Goods, Smt, Back neck Tape color not matching 2 type, Shade Tape, TOWN

Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's

Supplier's Representative

Factory Seal

STARTEX clothing company  
 Home-365,Road-06,Baridhara,DOHS,Dhaka-1206 Tel-88 02-8412073, 88 02-8470977  
 www.starTEX-clothing.com

Factory Name: Fast Fashion  
 Customer: House / LPP  
 Dept: LADIES KNIT  
 Production in Factory: House / LPP  
 Order no: 611165/62  
 Style: 159-505 Q-858  
 Description: LADIES BLOUSE  
 Ex-fac Date: 02-04-12  
 Packing way: Solid/Pcs  
 Ship status: SEA MOOD  
 Sample in Hand: Yes  
 poly bag in house: Yes  
 Carton in house: Yes  
 Sewing Lbl in house: Yes  
 Sticker in house: Yes  
 Loading status: 100%  
 DATE: 02-04-2012  
 Order Qty: 288+132=420  
 Ship Qty: 288+1310 Pcs  
 carton Qty: 21 Ctn  
 Insp Ratio: ADL-4.0  
 Loading Discrepancy: Yes  
 Per carton: See pack list

Sample Provided By:  Buyer  Supplier Russia/Poland  Factory  No Sample  
 AQL STANDARD - ANSE/ASQC Z1 4-2001 LEVEL-II (AQL -  1.5  2.5  4.0)

Color: OX CREAM  
 REQ Gsm:   
 Result:   
 ACCESSORIES:  Main Label ok  Hang tag ok  Price Sticker ok  Washing Instruction ok  Washing Symbol ok  spare button  zipper  Ribbon  Care LBL/size LBL/Tag  Shipping mark ok  Size of Carton/Meas ok  way of Pack ok  Way of folding Goods ok  Others

INSPECTED CARTON:

COLOR	Carton no	SOLID/PCS Inspection/Pcs	ASSORT/PRE PACK Carton No	Insp/Pcs
<u>OX CREAM</u>	<u>RUSSIA - C/NO - 02</u>			
	<u>POLAND - C/NO - 12, 10, 02, 15, 13</u>			<u>80 Pcs</u>

INSPECTION'S DETAILS:

Presentation/Make up Fault's	Major	Minor	Comment's	Status
<u>DISTY SPOT</u>	<u>    </u>			
<u>UNFINISHED SEAM</u>	<u>1</u>			
<u>SEWING PROBLEM</u>				
<u>UNCUT Thread</u>		<u>    </u>		
<u>STITCHING PROBLEM</u>	<u>1</u>	<u>    </u>		
<u>SEWING PROBLEM</u>		<u>    </u>		
<u>UPDOWN</u>			<u>Back front</u>	
<u>OPEN SEAM</u>	<u>  </u>			

RESUME OF INSPECTION:

	Accept	Problem		Accept	Problem	
Fabric Quality	<u>ok</u>		Decoration	<u>ok</u>		C-Critical
Color Dyeing	<u>ok</u>		Measurement		<u>B</u>	B-Big
Appearance	<u>ok</u>		Hangtag/Labels	<u>ok</u>		S-Small
Workmanship		<u>B</u>	Packing	<u>ok</u>		
Trimmings	<u>ok</u>		Other's			

SIGNATURE: [Signature]  
 Startex Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp Date: 02-04-12  
 Start Time: 09:00 Am/Pm  
 End Time: 02:00 Pm  
 SIGNATURE: [Signature]  
 Startex Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp Date: [Signature]  
 Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL 2.5  AQL 4.0  
 Inspected Qty: 88  
 ACCEPTED  
 R: REPACK (See pre pack report)

INSPECTION RESULT

<input type="checkbox"/> PASS	<input type="checkbox"/> FAILED	<input type="checkbox"/> RE CHECKED	<input type="checkbox"/> WAITING FOR APPROVAL
-------------------------------	---------------------------------	-------------------------------------	---

General Comment's of Inspection: LDN0 ctn Inside Empty space seen from Top Side also and show quality issue. propose objection that Authority taken.  
 Vendor or Suppliers Manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Supplier's Representative: [Signature]  
 Factory Seal: [Signature]



Factory Name: First Fashion (Pre-Production Inspection)  In-Line Inspection  Final Inspection  Re-Inspection

Customer: HOUSE / LPP Ship status: SCAMPOD DATE: 02-04-2013  
 Dept: LADIES KNIT Sample in Hand: YES Order Qty: 6240 Pcs  
 Production in Factory: 632155 poly bag in house: YES Ship Qty: 6120 Pcs  
 Order no: 130-010 PV-604 Carton in house: YES carton Qty: 64 Ctns  
 Style: LADIES T-SHIRT Sewing Lbl In house: YES Insp.Ratio: ADL-4.0  
 Description: LADIES T-SHIRT Sticker in house: YES Loading Discrepancy: YES  
 Ex-fac Date: 02-04-13 Loading status: 100% Per carton: See pack list  
 Packing way: \_\_\_\_\_

Sample Provided By:  Buyer  Supplier  Factory Assort/Pre Pack \_\_\_\_\_  
 AQL STANDARD - ANSI/ASQC Z1-2003 LEVEL-II (AQL -  1.5  2.5  4.0)

Color	REQ Gsm	Result
<u>CREAM LT. GREY</u>		
<u>Black</u>		

- ACCESSORIES**  
 Main Label OK  Hang tag 2  Price Sticker OK  Washing Instruction OK  washing Symbol OK  spare button \_\_\_\_\_  zipper \_\_\_\_\_  Button \_\_\_\_\_  Care LBL/size LBL/Tag \_\_\_\_\_  
**PACKING**  
 Shipping mark OK  Size of Carton/Meas OK  way of Pack OK  Way of folding Goods OK  Others \_\_\_\_\_

**INSPECTED CARTON:**

COLOR	Carton no	SOLID/PCS		ASSORT/PRE-PACK	
		Inspection/PCS	Carton No	Inspection/PCS	Inspection/PCS
<u>CREAM LT. GREY</u>	<u>C/N0-28 30 23, 01, 48, 34</u>				<u>125 Pcs</u>
<u>Black</u>					

**INSPECTION'S DETAILS:**

Presentation/Make up Fault's	Major	Minor	Comment's	Status
<u>POCKET POSITION</u>	I		<u>SIDE SEAM AREA</u>	
<u>POCKET STITCH</u>	III			
<u>STITCHING</u>		III/III		
<u>SLIP OFFEND UP/DOWN</u>	I	III		
<u>SLIP STITCH</u>				
<u>DRAWY SPDT</u>	II			
<u>BAD FINISH BOTTOM</u>	I	III		
<u>MEASUREMENT PROBLEM</u>	I			

**RESUME OF INSPECTION:**

	Accept	Problem		Accept	Problem	
Fabric Quality	<u>OK</u>		Decoration	<u>OK</u>		C-Critical
Color/Dyeing	<u>OK</u>		Measurement		<u>B</u>	B-Big
Appearance	<u>OK</u>		Hangtag/Labels		<u>2 type of Tag</u>	S-Small
Workmanship		<u>5</u>	Packing	<u>OK</u>		
Findings	<u>OK</u>		Other's			

**SIGNATURE**  
 Startex Clothing Company  
 Inspector Name: [Signature]  
 Designation: INSPECTOR  
 ID No: [Signature]  
 Insp Date: 02-04-13  
 Start Time: \_\_\_\_\_ Am/Pm  
 End Time: \_\_\_\_\_ Pm

**SIGNATURE**  
 Startex Clothing Company  
 Inspector Name: [Signature]  
 Designation: INSPECTOR  
 ID No: [Signature]  
 Insp Date: \_\_\_\_\_

Inspection Result: **QUALITY**  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL-2.5  AQL-4.0  
 Inspected Qty: 95  
 ACCEPTED  
 R: REPACK (See pre pack report)

Inspection Qty	<u>125</u>
Number of Major Faults	<u>11</u>
% of Major Faults	<u>8.8% / 15.2%</u>

**INSPECTION RESULT**  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: POCKET LENGTH & FOUND GREY COLOR. WHITE COLOR FABRIC. PREVIOUS POSITION TAG & NEW TO HANG TAG DIFFERENT TYPE.  
 Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Inspector Representative: [Signature] Factory Seal: \_\_\_\_\_

STARTEX clothing company  
 House-365, Road-06, Baridhara DOHS, Dhaka-1206. Tel-88 02-8412073, 88 02-8470977  
 www.starrex-clothing.com

Factory Name: HY FASHION  
 Customer: RESERVED / CPP  
 Dept: MEN'S WPT.  
 Production in Factory: INDIGO-1B  
 Order no: 2009011-1B  
 Style: 20-266  
 Description: 3T SWT. SHIRT  
 Ex-fac Date: \_\_\_\_\_  
 Packing way: \_\_\_\_\_

Ship status: AIR MODE  
 Sample in Hand: YES  
 poly bag in house: YES  
 Carton in house: YES  
 Sewing Lbl in house: YES  
 Sticker in house: YES  
 Loading status: 100%

DATE: 03-04-2017  
 Order Qty: 2821 2940 Pcs.  
 Ship Qty: 2521 2913 Pcs.  
 carton Qty: 38 Ctn.  
 Insp Ratio: AQL-2.5  
 Loading Discrepancy: Yes  
 Per carton: See Product

Sample Provided By:  Buyer  Supplier Russia/Poland  Factory  No Sample

AQL STANDARD - ANSI/ASQC Z1 4-2003 LEVEL II (AQL -  1.5  2.5  4.0)

Color: INDIGO-57X

ACCESSIONS  
 Main Label OK  Hang tag OK  Price Sticker OK  Washing Instruction OK  washing Symbol OK  
 Lbl OK  spare button  zipper  Button  Care LBL/size LBL/Flag

PACKING  
 Shipping mark  Size of Carton/Meas  way of Pack  Way of folding Goods  Others

COLOR	INSPECTED CARTON	
	CARTON NO	SOLID/PCS INSPECTION/PCS
INDIGO-57X	RUSSIA- 02	(Ctn) Number + Ctn weight need
	POLAND- 10, 12 20, 21, 25 31	125 Pcs.

INSPECTION'S DETAILS:

Presentation/Make up Fault's	Major	Minor	Comment's	Status
Bad finish shirt	III			
Knout-fold tuck				
Measurement problem	II			
Bad Neck size		III III		
Spinning problem		III		
Print Problem				

NOTE: Susine Point SHIRT ALSO FOUND INSPECTION TIME. MEASUREMENT NOT IN TOLERANCE. SOME AREA PRINT CAPLAPS FOUND INSPECTION TIME.

RESUME OF INSPECTION:

	Accept	Problem	Accept	Problem	
Fabric Quality	OK		OK		C-Critical
Color Dyeing	OK			B	B-Big
Appearance	OK		OK		S-Small
Workmanship		3	OK		
Trimings	OK		OK		

DAMAGE Ctn 5/3 Replace before Ex-factory

SIGNATURE  
 Starrex Clothing Company  
 Inspector Name: R. K. S.  
 Designation: \_\_\_\_\_  
 ID No: 0012  
 Insp Date: 03-04-17

SIGNATURE  
 Starrex Clothing Company  
 Inspector Name: \_\_\_\_\_  
 Designation: \_\_\_\_\_  
 ID No: \_\_\_\_\_  
 Insp date: \_\_\_\_\_

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL-2.5  AQL 4.0  
 Inspected Qty: 125  
 ACCEPTED  
 R-REPACK (See pre pack report)

Inspection Qty	125 Pcs.
Number of Major Faults	08
% of Major Faults	6.4% 8.8%

INSPECTION RESULT  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: Ctn Damage 5/3 Replace Ctn. Without Ctn sticker. NEED REPACK when Ex-factory.

Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's

Factory Seal

House-365,Road-06,BaridharaDOHS,Dhaka-1206.Tel-88-02-8412073, 88-02-8470977 (5)  
**STARTEX clothing company**  
 WWW.STARTEX-CLOTHING.COM

Factory Name: FIAT FASHION

Customer: House / LPP  
 Dept: WOOLS UNIT  
 Production in Factory: 615121-22  
 Order no: 615121-22  
 Style: 530-564-KI-530  
 Description: WOOLST-SHIRT  
 Ex-fac Date:  
 Packing way:

Ship status:  
 Sample in Hand: NO  
 poly bag in house: YES  
 Carton in house: YES  
 Sewing Lbl in house: YES  
 Sticker in house: YES  
 Loading status: 100%

DATE: 25/03/2012  
 Order Qty: 18214 + 15440  
 Ship Qty: 18214 + 13357  
 carton Qty: 15440  
 Insp Ratio: ADL-4.0  
 Loading Discrepancy: Yes  
 Per carton: 500 Pcs Ust

Solid/Pcs \_\_\_\_\_ Assort/Pre Pack \_\_\_\_\_  
 Sample Provided By:  Buyer  Supplier Russia + Poland  No Sample  
 AQL STANDARD - ANS/ASQC Z1 4-2003 LEVEL II (AQL:  1.5  2.5  4.0)

Color	REQ/Gsm	Result
<u>LT. Green</u>	<u>HOT PINK</u>	
<u>LT. Turquoise</u>		

ACCESSORIES  
 Main Label  Hang tag  Price Sticker  Washing Instruction  washing Symbol  spare button  zipper  Button  Care LBL/size LBL/Flag  
 PACKING  
 Shipping material  Size of Carton/Meas  way of Pack  Way of folding Goods:  Others

INSPECTED CARTON:

COLOR	SOLID/PCS		ASSORT/PRE-PACK	
	Carton no	Inspection/Pcs	Carton No	Insp/Pcs
<u>LT. Green</u>				
<u>LT. Turquoise</u>				<u>200 Pcs</u>

INSPECTION'S DETAILS:

Presentation/Make up Fault's	Major	Minor	Comment's	Status
<u>Stitching Problem</u>	<u>    </u>	<u>    </u>		
<u>Oil spot</u>	<u>  </u>	<u>   </u>		
<u>Dirty spot / Print spot</u>	<u>  </u>	<u>   </u>		
<u>Loose thread / frays</u>	<u>  </u>	<u>   </u>		
<u>UNEVEN Bottom</u>	<u>  </u>	<u>   </u>		
<u>Hole / fabric cut</u>	<u>    </u>			
<u>Broken stitch</u>	<u>  </u>			
<u>UNEVENNESS SEAM</u>	<u>   </u>			
<u>Iron problem</u>		<u>    </u>		

RESUME OF INSPECTION:

	Accept	Problem	Accept	Problem	
Fabric Quality	<u>OK</u>		Decoration	<u>OK</u>	C-Critical
Color/Dyeing	<u>OK</u>		Measurement	<u>B</u>	B-Big
Appearance	<u>OK</u>		Hangtag/Labels	<u>OK</u>	S-Small
Workmanship		<u>B</u>	Packing	<u>OK</u>	
Trimmings	<u>OK</u>		Other's		

SIGNATURE  
 Startex Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp Date: [Signature]  
 Start Time: [Signature] Am/Pm  
 End Time: [Signature] Pm

SIGNATURE  
 Startex Clothing Company  
 Inspector Name: [Signature]  
 Designation: [Signature]  
 ID No: [Signature]  
 Insp date: [Signature]

Inspection Result / QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL 2.5  AQL 4.0  
 Inspected Qty: 15  
 ACCEPTED  
 R: REPACK (See pre pack report)

Inspection Qty	<u>200</u>
Number of Major Faults	<u>16</u>
% of Major Faults	<u>8%</u>

INSPECTION RESULT  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: Quality Purpose Buyer Asking Discount. Discount 5/8  
Responsibility Fiat Fashion Avon-lye.

Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Supplier's representative \_\_\_\_\_ Factory Seal \_\_\_\_\_

Factory Name: Flat Position DATE: 17-04-2017  
 Customer: HOUSE / LPP Ship status: SEA MODE Order Qty: 1680 Pcs  
 Dept: MEN'S POLO Sample in Hand: YES Ship Qty: 1680 Pcs  
 Production in Factory: YES poly bag in house: YES carton Qty: 2 B.C.N.  
 Order no: 622411 Carton in house: YES Insp. Ratio: ADL 4:0  
 Style: POM-302 BL-519 Sewing Lbl In house: YES Loading Discrepancy: NO  
 Description: MEN'S POLO Sticker in house: YES Per carton: See pack list  
 Ex-fac Date: 17-04-2017 Loading status: 100%  
 Packing way: Solid Pcs 780 Pcs Assort/Pre Pack: 900 Pcs

Sample Provided By:  Buyer  Supplier RUSSIA  Factory  No Sample  
 AQL STANDARD - ANS/ASQC Z1 4-2003 LEVEL II (AQL -  1.5  2.5  4.0)

**ACCESSORIES**  
 Main Label OK  Hang tag OK  Price Sticker OK  Washing Instruction OK  washing Symbol OK  spare button  zipper  Button  Care LBL/size LBL/Flag LBL OK  
**PACKING**  
 Shipping mark OK  Size of Carton/Meas. OK  way of Pack OK  Way of folding Goods: OK  Others

**INSPECTED CARTON:** 58x40x

COLOR	SOLID/PCS		ASSORT/PRE-PACK	
	Carton no	Inspection/Pcs	Carton No	Insp/Pcs
<u>WHITE, NAVY</u>				
<u>Mid Green</u>	<u>C/ND-13, 05, 11, 18, 26, 24</u>			<u>80 Pcs</u>

**INSPECTION'S DETAILS:**

Presentation/Make up Fault's	Major	Minor	Comment's	Status
<u>SEWING Problem</u>		<u>III</u>		<input checked="" type="checkbox"/>
<u>Worst Thread</u>		<u>III</u>		<input checked="" type="checkbox"/>
<u>Iron Problem</u>		<u>III</u>		
<u>MARK Hole</u>	<u>I</u>		<u>EMB AREA HOLE</u>	
<u>Unseen Bottom Staff</u>	<u>I</u>			
<u>Black F problem</u>	<u>II</u>			
<u>Dirty spot</u>	<u>I</u>			
<u>Pattern problem</u>	<u>II</u>			
<u>Bad Staff</u>		<u>II</u>		

**RESUME OF INSPECTION:**

	Accept	Problem	Accept	Problem	
Fabric Quality	<u>OK</u>		Decoration	<u>OK</u>	C-Critical
Color/Dyeing	<u>OK</u>		Measurement	<u>B</u>	B-Big
Appearance	<u>OK</u>		Hangtag/Labels	<u>OK</u>	S-Small
Workmanship	<u>OK</u>		Packing	<u>OK</u>	
Trimmings	<u>OK</u>		Other's		

**SIGNATURE**  
 Startex Clothing Company  
 Inspector Name: \_\_\_\_\_  
 Designation: \_\_\_\_\_  
 ID No: \_\_\_\_\_  
 Insp date: \_\_\_\_\_

**Inspection Result - QUALITY**  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL 2.5  AQL 4.0  
 Inspected Qty: 15 Pcs  
 ACCEPTED  
 R: REPACK (See pre pack report)

Start Time: _____ Am/Pm	Inspection Qty: <u>80 Pcs</u>
End Time: _____ Pm	Number of Major Faults: <u>01</u>
	% of Major Faults: <u>1.25%</u>

**INSPECTION RESULT**  
 PASS  FAILED  RE CHECKED  WAITING FOR APPROVAL

General Comment's of Inspection: City Marked Double Number found. Old Color Dirty Spot found. Emb Stitches covering not proper.

Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Supplier's Representative: \_\_\_\_\_ Factory Seal: \_\_\_\_\_

Factory Name: Final Fashion       Pre-Production Inspection     In-Line Inspection     Final Inspection     Re-Inspection      DATE: 17-04-2017

Customer: HOUSE 1 LPP      Ship status: SEA MODE      Order Qty: 960 Pcs  
 Dept: LADIES KNIT      Sample in Hand: YPS      Ship Qty: 960 Pcs  
 Production in Factory:      poly bag in house: YPS      carton Qty: 8 Ctns  
 Order no: 618430      Carton in house: YPS      Insp Ratio: ADL-2-4.0  
 Style: TLD-528/KI-901      Sewing Lbl in house: YPS      Loading Discrepancy: NO  
 Description: LADIES BLOUSE      Sticker in house: YPS      Per carton: See pack list  
 Ex-fac Date: 17-04-2017      Loading status: 100%

Solid/Pcs: \_\_\_\_\_      Assort/Pre Pack: \_\_\_\_\_  
 Sample Provided By:  Buyer     Supplier     Factory     No Sample  
RUSSIA      (AQL -  1.5     2.5     4.0)

**AQL STANDARD - ANSI/ASQC Z1 4-2003 LEVEL-II**

Color	REQ Gsm	Result
<u>CREAM-OK</u>		
<u>HOT PINK-42x</u>		
<u>TURDUISE-60x</u>		

**ACCESSORIES**  
 Main Label OK     Hang tag OK     Price Sticker OK     Washing Instruction OK  
 Symbol OK     spare button     zipper     Ribton     Care LBL/size LBL/Flag

**PACKING**  
 Shipping mark OK     Size of Carton/Meas OK     way of Pack OK     Way of folding  
 Goods: OK    Others: \_\_\_\_\_      58x40x55

**INSPECTED CARTON:**

COLOR	SOLID/PCS		ASSORT/PRE-PACK	
	Carton no	Inspection/Pcs	Carton No	Insp/Pcs
<u>CREAM HOT PINK</u>		<u>Randomly Pick up.</u>		<u>50 Pcs</u>
<u>TURDUISE</u>				

**INSPECTION'S DETAILS:**

Presentation/Make up Fault's	Major	Minor	Comment's	Status
<u>SPRING Problem</u>	II	III	<u>LOG UNWEN. X POSITION AREA.</u>	
<u>Placket unweven</u>	III			
<u>Neck</u>				
<u>Button hole</u>				
<u>Distort sept.</u>	I			
<u>Drawn stitch</u>	I			
<u>Neck shape problem</u>		III	<u>Button attached Area.</u>	
<u>UNCUT Thread</u>				

**RESUME OF INSPECTION:**

	Accept	Problem	Accept	Problem	
Fabric Quality	<u>OK</u>		<u>OK</u>		C-Critical
Color/Dyeing	<u>OK</u>			<u>B</u>	B-Big
Appearance	<u>OK</u>		<u>OK</u>		S-Small
Workmanship		<u>B</u>		<u>Bilister Poly Felle NOT actual. MGRS.</u>	
Trimings	<u>OK</u>				

**SIGNATURE**  
 StarTex Clothing Company  
 Inspector Name: \_\_\_\_\_  
 Designation: \_\_\_\_\_  
 ID No: \_\_\_\_\_  
 Insp Date: \_\_\_\_\_

**SIGNATURE**  
 StarTex Clothing Company  
 Inspector Name: \_\_\_\_\_  
 Designation: \_\_\_\_\_  
 ID No: \_\_\_\_\_  
 Insp date: \_\_\_\_\_

**Inspection Result QUALITY**  
 AQL 2.5     AQL 4.0  
 Pre Pack  
 AQL 2.5     AQL 4.0  
 Inspected Qty: 12 Pcs  
 ACCEPTED  
 R: REPACK (See pre pack report)

**INSPECTION RESULT**  
 PASS     FAILED     RE CHECKED     WAITING FOR APPROVAL

General Comment's of Inspection: This Qty Accept with conditionally. Buyer Asking Discount for Quality Issue. Final Fashion Take Responsibility.

Vendor or Supplier: Manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Supplier/Factory Representative: \_\_\_\_\_      Factory Seal: \_\_\_\_\_

STARTEX clothing company  
House: 365, Road-06, Baridhara DOHS, Dhaka-1206 Tel: 88 02-8412073, 88 02-8470977

www.startex-clothing.com

Factory Name: Final Fashion DATE: 30-04-2017  
 Customer: RESERVED 11 PP Ship status: SCAMONE Order Qty: 19,600 Pcs.  
 Dept: MEN'S KNIT Sample in Hand: Yes Ship Qty: 19,231 Pcs.  
 Production in Factory: Yes poly bag in house: Yes carton Qty: 195 Chn  
 Order no: 19090 Carton in house: Yes Insp Ratio: ADL-2.5  
 Style: R-USD Sewing Lbl in house: Yes Loading Discrepancy: Yes  
 Description: MEN'S KNIT Sticker in house: Yes Per carton: See pack list  
 Ex-fac Date: \_\_\_\_\_ Loading status: 100%  
 Packing way: \_\_\_\_\_ Assort/Pre Pack: 11270 Pcs.

Sample Provided By:  Buyer  Supplier POLAND  Factory  No Sample  
 AQL STANDARD - ANSEASQC714-2001 LEVEL-11 (AQL -  1.5  2.5  4.0)

Color: WHITE - ODX Result: OK ACCESSORIES:  Main Label OK  Hang tag OK  Price Sticker OK  Washing Instruction OK  
Blue 95% Black 5%  Spaced button  zipper  Buttons  Care LBL/size LBL/flag  
 LBL: OK PACKING:  Shipping mark OK  Size of Carton/Meas: P  way of Pack: OK  Way of folding: \_\_\_\_\_  
 Others: \_\_\_\_\_

INSPECTED CARTON

COLOR	Carton no	SOLID PCS Inspection/Pcs	ASSORT/PRE PACK Carton No	Inspe/Pcs
WHITE Local	4ND	13, 07, 12, 11, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30		
Blue, Black		13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30		200 Pcs

INSPECTION'S DETAILS

Presentation/Make up Fault's	Major	Minor	Comment's	Status
Print Spot	I			
Bottom UPDOWN	III	III		
Brown stain	III			
Oil spot	III			
SL UPDOWN/Slipstitch	II			
Dusty spot	II			
Spindle Problem	I	II		
Plant	I			
Hole	II			
DIRTY Neck		III		
Wool Tuck	I			
Needle Mark		I		
Appearance	II			
Insect				

*Note: Grade Directly not Acceptable  
Buyer Asking discount  
S/G. Romen flat garment  
Authority.*

RESUME OF INSPECTION

	Accept	Problem	Accept	Problem	
Fabric Quality	OK		OK		C Critical
Color/Dyeing		B		B	B Big
Appearance	OK		OK		S Small
Workmanship		B		B	
Trainings	OK				

SIGNATURE  
Startex Clothing Company  
Inspector Name: [Signature]  
Designation: \_\_\_\_\_  
ID No: 0012  
Insp Date: 30-04-17

SIGNATURE  
Startex Clothing Company  
Inspector Name: \_\_\_\_\_  
Designation: \_\_\_\_\_  
ID No: \_\_\_\_\_  
Insp date: \_\_\_\_\_

Inspection Result - QUALITY  
 AQL 2.5  AQL 4.0  
 Pre Pack  
 AQL-2.5  AQL 4.0  
 Inspected Qty  
 ACCEPTED  
 R: REPACK (See pre pack report)

Inspection Qty	200
Number of Major Faults	26 18
% of Major Faults	13% 9%

INSPECTION RESULT

PASS  FAILED  RE-CHECKED  WAITING FOR APPROVAL

General Comments of Inspection: CLW damaged S/G because of moisture. General inside factory free from any other problem.

Vendor or Supplier's Manufacturing are hold fully responsibility for any defects and claims from the buyer's.

Supplier/Factory Representative

Factory Seal



# NAFISA INT'L TRADING (BD) LTD.

(100% Export-oriented Garments Buying House)

Plot # 06, Road # 1/A, Gulshan-1, Dhaka-1212, Bangladesh. Tel : +8802 9886536  
 9884003, 9856530, 9857142, +88 09808333222 (Hunting); Fax : +88 02 58811313  
 E-mail : info@nafisabd.com, nafisabd@bdcom.com, web : www.nafisabd.com

19188

## FINAL INSPECTION REPORT

Buyer	Supplier	Date
Article/style	Order Qty	Carton Qty
Order No.	Inspection qty	Constr / Gsm/GG
Description	Fabrication	
Inspector Name	Assortment	Mode of Ship
Q.C Name		

Accessories & others details	Main Label	<input checked="" type="checkbox"/>	Sticker/Barcode	<input type="checkbox"/>	Inlay/photo card	<input type="checkbox"/>	Shipping Mark : front & back / Side
	Size Label	<input type="checkbox"/>	Poly Indv / Blstr	<input checked="" type="checkbox"/>	Belly Band	<input type="checkbox"/>	Shipping Mark : Ok /not ok
	Care Label	<input checked="" type="checkbox"/>	Poly Sticker	<input type="checkbox"/>	Button	<input type="checkbox"/>	Ctn Mes. x x cm
	Tab Label	<input type="checkbox"/>	Lining	<input type="checkbox"/>	Zipper	<input type="checkbox"/>	GW. NW.
	Hang Tag	<input type="checkbox"/>	Eylet / Stoper	<input type="checkbox"/>	Hanger	<input type="checkbox"/>	Qty/ per ctn
	Price Tag	<input checked="" type="checkbox"/>	Tissue	<input type="checkbox"/>	Others	<input type="checkbox"/>	

Lot Size	Normal Sample			Acceptable Quality Level											
	1	5	10	1.5			2.5			4.5			8.5		
51-90	5	13	20	0	1	0	1	1	0	1	2	1	2	3	
91-150	8	20	32	0	1	1	0	1	2	1	2	3	1	3	5
151-200	13	32	50	0	1	2	1	2	3	1	3	5	2	5	7
201-500	20	50	80	1	2	3	1	3	5	2	5	7	3	7	10
501-1200	32	80	125	1	3	5	2	5	7	3	7	10	5	10	14
1201-3200	50	125	200	2	5	7	3	7	10	5	10	14	7	14	21

Note- ♣ Level-1 Norm ♣ Level-2 Reduced ♣ Level-3 Tightened

Ctn #	Colour	Pcs	Defect Details	Critical	Major	Minor
			Total			

Remarks :	<b>Inspection Result</b> Pass <input type="checkbox"/> Re-check <input type="checkbox"/> Hold <input type="checkbox"/> Rejected <input type="checkbox"/>
-----------	--

Inspected By \_\_\_\_\_ Vendors Acknowledgement \_\_\_\_\_

Original -QC, Yellow Copy -M/R, Green Copy -Vendor

2

ICL FASHION  
FINAL INSPECTION  
House 70 Road 16 Block A  
Banani Dhaka 1212

Inspected by: EDP  
Date: 30/06/18

Style: <u>CEFTICE</u>		Inspected by: <u>EDP</u>	
Manufacturer: <u>41825 A/Cash to 7</u>		Factory: <u>5107/11</u>	
Description: <u>2DS E/SAV PRINTED</u>		Country of Origin: <u>INDIA</u>	
Fabric: <u>100% COT</u>		Color: <u>WHITE, BLUE, RED, CEMENT</u>	
Weight: <u>140 GSM</u>		Production Code: <u>2000</u>	
Production Status			
Lot No: <u>316</u>		Total No. of Lots: <u>260 C.T. 11</u>	
Lot No. List: <u>OK, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50</u>			
Packing & Marking			
Qty: <u>2 Lot</u>	Single: <input checked="" type="checkbox"/>	Double: <input type="checkbox"/>	
Label: <input type="checkbox"/>	Master Ckt: <input type="checkbox"/>		
ASSIGNMENT		Color Checked: <input checked="" type="checkbox"/>	Count Checked: <input type="checkbox"/>
Attached Label/Assigned Size: <input type="checkbox"/>		Assigned Color/Size: <input type="checkbox"/>	
Shipping Mark: <input type="checkbox"/>	Mark: <input type="checkbox"/>	Label: <input type="checkbox"/>	
Net Kilo City: <input type="checkbox"/>	Ship: <input type="checkbox"/>	Open: <u>13.5M</u>	Short: <input type="checkbox"/>
Carton Dimension: <input type="checkbox"/>	Carton Weight: <input type="checkbox"/>	Net Weight: <input type="checkbox"/>	
Inspection Conclusion			
Inspection Level: <u>316</u>			
Sample Size: <u>316</u>			
Critical Defects: <input type="checkbox"/>	Allowed: <input type="checkbox"/>	Found: <input type="checkbox"/>	
Major Defects: <input type="checkbox"/>	Allowed: <u>14</u>	Found: <u>15</u>	
Minor Defects: <input type="checkbox"/>	Allowed: <u>81</u>	Found: <u>13</u>	
Informative Observation			
Inspection Environment			Other: <input type="checkbox"/>
Lighting: <input type="checkbox"/>	Daylight: <input checked="" type="checkbox"/>	Room Light: <input checked="" type="checkbox"/>	Outdoor: <input type="checkbox"/>
Inspection Place: <input checked="" type="checkbox"/>	Factory Workshop: <input type="checkbox"/>	Store House: <input type="checkbox"/>	
Time: <u>10:00 AM</u>	Table: <input checked="" type="checkbox"/>	Top of Ctn: <input type="checkbox"/>	
Temperature: <input checked="" type="checkbox"/>	Warm: <input type="checkbox"/>	Dry: <input type="checkbox"/>	
Weather Condition: <input type="checkbox"/>	Windy: <input type="checkbox"/>	Dry: <input checked="" type="checkbox"/>	
Inspection Time: <input checked="" type="checkbox"/>	Day: <input checked="" type="checkbox"/>	Night: <input type="checkbox"/>	
Condition of Sample of Code of Contract can be observed	Yes/No		
Comply with Needle Policy	Yes/No		
All Garments Passed metal detection	Yes/No	With record	Yes/No
Recommendation on correction:			
OVER ALL RESULT: <u>(PASS)</u>			
Lot Description: <u>OK TO SHIP OUT</u>		If Re-inspection Required, When: <u>NA</u>	
Inspector: <u>[Signature]</u>		Representative of Buying House: <u>[Signature]</u>	





**ICL FASHION**  
**FINAL INSPECTION**  
 House-7B Road-16 Block-A  
 Banani, Dhaka-1212

Report No ①  
 Date 30/6

Measurement Check							
All Measurement within tolerance			Yes/No		Comments wash item		
Remarks							
Quality Audit							
Inspector used	Defect Description	AQL Applied	Sample Size	Acceptable	Minor		
					Critical	Major	Minor
	REJECT ✓				03		
	BACK STITCH ✓				03		
	DARTY SPOT ✓				01	02	
	PRINT SPOT ✓				02	05	
	BOTTOM INTERIOR ✓					04	
	UNCUT THREAD ✓				02	04	
	ARM HOLE ERASER SHAPED ✓				01	02	
	Twisting ✓					02	
					Actual Faults	12	15
					Acceptable	14	21

ATTNY TO MR SHAHIDUL / PAKHABUR  
 WE FOUND PROVE PROBLEM. IF ANY PROBLEM  
 FROM BUYER SIDE. THEN FULLY  
 RESPONSIBLE BY FACTORY.

OK TO SHIP OUT  
 (PASS)

Inspector:  / No inspection Required: \_\_\_\_\_  
 Representative of Buyer: 

13

ICL FASHION  
FINAL INSPECTION  
House-79, Road-16, Block-A,  
Banani, Dhaka-1212

Report No. ①  
Date 23/10/18

Buyer: <b>LEFTIES</b>	Inspected by: <b>RAPPY</b>
Buyer Ref/Order No: <b>64009-K/DARK</b>	Factory: <b>FIAT FAS. LTD.</b>
Description: <b>MEN'S PRINTED T-SHIRT</b>	Name of QA: <b>MAMUN</b>
Fabricator: <b>100% COT. S/S</b>	Mode of Shipment: <b>SEA</b>
Color: <b>250, 251, 262, 750, 800, 803</b>	Time In: _____
Wash: <b>155 GSM</b>	Order Quantity: <b>28660</b>
	Shipped Qty: <b>28660</b>
	Shipment Date: _____
	Inspector: <b>1/2/3/4</b>

**Production Status**

Checked: <b>3/2</b>	Polybag: _____	Carton: _____	Total No. of Carton: <b>407 C.T. of</b>
Carton NBR Drawn: <b>03, 14, 36, 55, 66, 74, 98, 105, 128, 132, 145, 161, 171, 187, 197, 212, 206, 236, 244, 260, 267, 303, 326, 346, 403.</b>			

**Packing & Marking**

Poly: _____	Single: <input checked="" type="checkbox"/>	Blister: _____
Carton: _____	Inner Ctn: _____	Master Ctn: <input checked="" type="checkbox"/>
Assortment: _____	Solid Color/Solid Size: <input checked="" type="checkbox"/>	Color/Assorted Size: _____
	Assorted Color/Assorted Size: _____	Assorted Color/Solid Size: _____
Shipping Mark: _____	Main: _____	Side: _____
Per Ctn Qty: _____	Ship: _____	Over: _____
		Short: _____
Carton Dimension: _____	Gross Weight: _____	Net Weight: _____

**Inspection Conclusion**

Inspection Level: <b>2.5</b>			
Sample Size: <b>3/2</b>			
Critical Defects: _____	Allowed: _____	Found: _____	
Major Defects: _____	Allowed: <b>14</b>	Found: <b>10</b>	
Minor Defects: _____	Allowed: <b>31</b>	Found: <b>15</b>	



**Informative Observation**

Inspection Environment				Other
Lighting	<input type="checkbox"/> Daylight	<input checked="" type="checkbox"/> Room Light	<input type="checkbox"/> sufficient	<input type="checkbox"/>
Inspection Place	<input checked="" type="checkbox"/> Factory Workshop	<input type="checkbox"/> Ware House	<input type="checkbox"/>	<input type="checkbox"/>
Inspection Done On	<input checked="" type="checkbox"/> Table	<input type="checkbox"/> Top of Ctn	<input type="checkbox"/>	<input type="checkbox"/>
Cleanliness	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/>	<input type="checkbox"/>
Weather Condition	<input type="checkbox"/> Rainy	<input checked="" type="checkbox"/> Dry	<input type="checkbox"/>	<input type="checkbox"/>
Inspection Time	<input type="checkbox"/> Day	<input checked="" type="checkbox"/> Night	<input type="checkbox"/>	<input type="checkbox"/>

Evidence on breach of Code of Conduct can be observed: Yes/No \_\_\_\_\_  
 Comply with Needle Policy: Yes/No \_\_\_\_\_  
 All Garments Passed metal detection: Yes/No \_\_\_\_\_ With record: Yes/No \_\_\_\_\_  
 Recommendation on correction: **444 FOUND PRINT SHADE**

**VEIRATION**

OVER ALL RESULT: **(PASS)**

Lot Disposition: Release/Hold **OK TO SHIP OUT** If Re-Inspection Required, When: \_\_\_\_\_  
 Accepted by:  Representative of Buying House: 

**ICL FASHION**  
**FINAL INSPECTION**  
 House-79, Road-16, Block-A,  
 Banani, Dhaka-1212

Report No. ①  
 Date 23/10/18

Measurement Check					
All Measurement within tolerance		Yes/No	Garments wash item		Yes/No
Remark					
Quality Audit					
Single/Double Sampling		Sample Size		Major	Minor
Inspection Level		AQL Applied	Acceptable		
Defect Description	Comment/Position	Critical	Major	Minor	
RATIO MISSTAKE ✓			01		
REJECT ✓			03		
WROKED STITCHY ✓			02		
TWISTING ✓			01	02	
PART SHADING ✓			01		
RIB SHADING ✓				01	
DARTY SPOT ✓				03	
OIL MARK ✓				02	
FORGOTTEN YERN ✓				01	
CARE LABEL DAMAGE ✓			01		
POOR CK. SHAPE				05	
BOTTOM UNEVEN				01	
PRINT UNEVEN			01		
Actual Faults			10	15	
Acceptable			14	21	
Comments: ATTN :- TO MR. SHAHIDUL / MAHABUB WE FOUND ABOVE PROBLEM. IF ANY PROBLEM FROM BUYER SIDE. THEN FULLY RESPONSABLE BY FACTORY.					
OK TO SHIP OUT (PASS)					

Lot Disposition: Release/Hold

If Re-inspection Required, When

Accepted by:  Representative

 Representative of Buying House

④

**ICL FASHION**  
**FINAL INSPECTION**  
 House-79, Road-16 Block-A  
 Banani, Dhaka-1212

Report No. ①  
 Date: 11/07/18

Buyer: <b>LEFTIES</b>	Inspected By: <b>BAPPY</b>
Buyer Ref/Order No: <b>41847-K</b>	Factory: <b>FIAT FAS. LTD.</b>
Description: <b>GIRL'S L/SLV T-SHIRT</b>	Name of QA: <b>MAMUN</b>
Fabrication: <b>57% VISCOSE 41% LYPERAZO RIB</b>	Mode of Shipment: <b>SEA</b>
Color: <b>WHITE, NAVY BLUE, FUCHSIA</b>	Order Quantity: <b>11950</b>
Wash: <b>200 GSM</b>	Shipment Date: _____
Shipped Qty: <b>11381 PCS</b>	
Inspection: ②/ 3/ 4/	

Production Status			
Checked: <b>315</b>	Polybag: _____	Carton: _____	Total No. of Carton: <b>125 C.T.N</b>
Carton NBR Drawn: <b>01, 04, 09, 14, 26, 27, 40, 45, 47, 51, 54, 60, 67, 76, 87, 89, 93, 97, 105, 110, 122</b>			

Packing & Marking			
Only _____	Single: <input checked="" type="checkbox"/>	Blister: <input type="checkbox"/>	
Carton _____	Inner Ctn: <input type="checkbox"/>	Master Ctn: <input checked="" type="checkbox"/>	
Assortment _____	Solid Color/Solid Size: <input checked="" type="checkbox"/>	Color/Assorted Size: <input type="checkbox"/>	
	Assorted Color/Assorted Size: <input type="checkbox"/>	Assorted Color/Solid Size: <input type="checkbox"/>	
Shipping Mark _____	Main: _____	Side: _____	
Per Ctn Qty: _____	Ship: _____	Over: _____	Short: <b>569 PCS</b>
Carton Dimension: _____	Gross Weight: _____	Over: _____	Net Weight: _____



  

Inspection Conclusion			
Inspection Level: <b>2.5</b>			
Sample Size: <b>315</b>			
Critical Defects: _____	Allowed: _____	Found: _____	
Major Defects: _____	Allowed: <b>14</b>	Found: <b>08</b>	
Minor Defects: _____	Allowed: <b>21</b>	Found: <b>17</b>	

Informative Observation			
Inspection Environment:			Other: _____
Lighting: <input type="checkbox"/> Daylight	<input checked="" type="checkbox"/> Room Light	<input type="checkbox"/> sufficient	<input type="checkbox"/>
Inspection Place: <input checked="" type="checkbox"/> Factory Workshop	<input type="checkbox"/> Ware House	<input type="checkbox"/>	<input type="checkbox"/>
Inspection Done On: <input checked="" type="checkbox"/> Table	<input type="checkbox"/> Top of Ctn	<input type="checkbox"/>	<input type="checkbox"/>
Cleanliness: <input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/>	<input type="checkbox"/>
Weather Condition: <input type="checkbox"/> Rainy	<input checked="" type="checkbox"/> Dry	<input type="checkbox"/>	<input type="checkbox"/>
Inspection Time: <input type="checkbox"/> Day	<input checked="" type="checkbox"/> Night	<input type="checkbox"/>	<input type="checkbox"/>
Evidence on breach of Code of Conduct can be observed: _____	Yes/No: _____		
Comply with Needle Policy: _____	Yes/No: _____		
All Garments Passed metal detection: _____	Yes/No: _____	With record: _____	Yes/No: _____
Recommendation on correction: <b>*** FOUND MEASUREMENT DISCREPANCY</b>			



OVER ALL RESULT: <b>(PASS)</b>
Lot Disposition: <b>Release/Hold OK TO SHIP OUT</b> If Re-inspection Required, When: _____
Accepted by:  Factory Representative
Representative of Buying House: 

**ICL FASHION**  
**FINAL INSPECTION**  
 House-79, Road-16 Block-A  
 Banani, Dhaka-1212

Report No ①  
 Date 11/07/18

Measurement Check					
All Measurement within tolerance		Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Garments wash item		Yes/No
Remark					
Quality Audit					
Single/Double Sampling		AQL Applied		Sample Size	
Inspection Level		Acceptable		Major Minor	
Defect Description		Comment/Position		Major	Minor
PLIT ✓			Critical	01	
STRIP UPDOWN ✓				02	03
POOR OK. SHAPE ✓				02	04
SLV JOINT SHARPLY ✓				01	03
DARTY SPOT ✓					02
CUT AT SIDE SEAM ✓				01	
MAIN LBL SLANTED ✓					02
TWISTING ✓				01	
CROSS POINT UPDOWN					03
				1	1
Actual Faults				08	17
Acceptable				14	21
Comments: ATTORNEY TO MR. SHAHIDUL/MAHABUB WE FOUND ABOVE PROBLEM. OF APOLY PROBLEM FROM BUYER SIDE. THAT FULLY RESPONSIBLE BY FACTORY.					
OK TO SHIP OUT (PASS)					

Lot Disposition:  Release  Hold If Re-inspection Required, When \_\_\_\_\_

Accepted by:  Factory Representative Representative of Buying House: 

5

**ICL FASHION  
FINAL INSPECTION**  
House-79, Road-16, Block-A,  
Banani, Dhaka-1212

Report No. ①  
Date 27/09/18


Buyer: <b>PULL AND BEAR</b>	Inspected By: <b>BABBY</b>	Factory: <b>FIAT FAS. LTD.</b>
Buyer Ref/Order No: <b>30353-W</b>	Name of QA: <b>MAMUN</b>	Mode of Shipment: <b>SEA</b>
Description: <b>MEN'S S/S AOP T-SHIRT</b>	Time In: _____	Out: _____
Fabrication: <b>100% COT. S/S (AOP)</b>	Order Quantity: <b>3600</b>	Shipped Qty: <b>3533 PCS</b>
Color: <b>WHITE, NAVY BLUE</b>	Shipment Date: _____	Inspector: <b>①</b> / 3 / 4
Wash: <b>GSM 155</b>	<b>Production Status</b>	
Checked: <b>200</b>	Polybag: _____	Carton: _____
Carton NBR Drawn: <b>02, 10, 14, 18, 20, 26, 32, 36</b>	Total No. of Carton: <b>38 C.T. of</b>	
<b>Packing &amp; Marking</b>		
Poly: _____ Single: <input checked="" type="checkbox"/>	Blister: <input type="checkbox"/>	
Carton: _____ Inner Ctn: <input type="checkbox"/>	Master Ctn: <input checked="" type="checkbox"/>	
Department: _____	Sold Color/Sold Size: <input checked="" type="checkbox"/>	Color/Assorted Size: _____
	Assorted Color/Assorted Size: _____	Assorted Color/Sold Size: _____
Shipping Mark: _____	Main: _____	Side: _____
Per Ctn Qty: _____	Ship: _____	Over: _____
Carton Dimension: _____	Gross Weight: _____	Net Weight: <b>67 PCS</b>
<b>Inspection Conclusion</b>		
Inspection Level: <b>2.5</b>		
Sample Size: <b>200</b>		
Critical Defects: _____	Allowed: _____	Found: _____
Major Defects: _____	Allowed: <b>10</b>	Found: <b>08</b>
Minor Defects: _____	Allowed: <b>4</b>	Found: <b>10</b>
<b>Informative Observation</b>		
Inspection Environment		
Lighting: _____ Daylight: <input checked="" type="checkbox"/>	Room Light: <input checked="" type="checkbox"/>	Sufficient: <input type="checkbox"/>
Inspection Place: <input checked="" type="checkbox"/>	Factory Workshop: <input type="checkbox"/>	Ware House: <input type="checkbox"/>
Inspection Done On: <input checked="" type="checkbox"/>	Table: <input type="checkbox"/>	Top of Ctn: <input type="checkbox"/>
Cleanliness: <input checked="" type="checkbox"/>	Clean: <input type="checkbox"/>	Dirty: <input type="checkbox"/>
Weather Condition: <input checked="" type="checkbox"/>	Rainy: <input type="checkbox"/>	Dry: <input type="checkbox"/>
Inspection Time: <input checked="" type="checkbox"/>	Day: <input type="checkbox"/>	Night: <input type="checkbox"/>
Evidence on breach of Code of Conduct can be observed	Yes/No	
Comply with Needle Policy	Yes/No	
All Garments Passed metal detection	Yes/No	With record: Yes/No
Recommendation on correction		
<b>OVER ALL RESULT (PASS)</b>		
Lot Disposition: Release/Hold <b>OK TO SHIP OUT</b>	If Re-inspection Required, When: _____	
Inspector: <b>[Signature]</b>	Representative of Buying House: <b>[Signature]</b>	



6

**ICL FASHION  
FINAL INSPECTION**  
House-79, Road-16, Block-A  
Banani, Dhaka-1212

Report No. ①  
Date: 30/05/18

Buyer: <b>PULL AND BEAR</b>	Inspected By: <b>BAPPY</b>	Factory: <b>FIAT PAS. LTD.</b>
Buyer Ref/Order No: <b>65485-N/65487-N</b>	Name of QA: <b>MADHUN</b>	Made of Shipment: <b>AIR</b>
Description: <b>MEN'S PRINTED T-SHIRT</b>	Time in:	Out:
Fabrication: <b>100% COT. S/J</b>	Order Quantity: <b>35563</b>	Shipped Qty: <b>35371 PCS</b>
Color: <b>WHITE-260, NAVY-401</b>	Shipment Date:	Inspector: ① 2 3 4
Wash: <b>180 GSM</b>		
Production Status		
Checked: <b>600</b>	Polybag:	Carton:
Carton NBR Drawn: <b>03, 24, 51, 71, 86, 100, 137, 146, 161, 176, 202, 224, 05, 22, 34, 53, 69, 93, 113, 128, 147, 164, 182,</b>		Total No. of Carton: <b>413 CTON.</b>
Packing & Marking		
1/2 Lot Single: <input checked="" type="checkbox"/>	Blister: <input type="checkbox"/>	
Carton: Inner Ctn: <input type="checkbox"/>	Master Ctn: <input checked="" type="checkbox"/>	
Assortment:	Solid Color/Solid Size: <input checked="" type="checkbox"/>	Color/Assorted Size: <input type="checkbox"/>
	Assorted Color/Assorted Size: <input type="checkbox"/>	Assorted Color/Solid Size: <input type="checkbox"/>
Shipping Mark: Main: <input type="checkbox"/> Side: <input type="checkbox"/>		
Per Ctn Qty: <input type="checkbox"/>	Shp. Over: <input type="checkbox"/>	Shor: <b>192 PCS</b>
Carton Dimension:	Gross Weight:	Net Weight:
Inspection Conclusion		
Inspection Level: <b>2.5</b>		
Sample Size: <b>500</b>		
Critical Defects: <input type="checkbox"/>	Allowed: <input type="checkbox"/>	Found: <input type="checkbox"/>
Major Defects: <input type="checkbox"/>	Allowed: <b>21</b>	Found: <b>14</b>
Minor Defects: <input type="checkbox"/>	Allowed: <b>21</b>	Found: <b>21</b>
Informative Observation		
Inspection Environment:		Other: <input type="checkbox"/>
Lighting: <input type="checkbox"/> Daylight <input checked="" type="checkbox"/> Room Light <input type="checkbox"/> Sufficient <input type="checkbox"/>		
Location Place: <input checked="" type="checkbox"/> Factory Workshop <input type="checkbox"/> Ware House <input type="checkbox"/>		
Inspection Done On: <input checked="" type="checkbox"/> Table <input type="checkbox"/> Top of Ctn <input type="checkbox"/>		
Cleanliness: <input checked="" type="checkbox"/> Clean <input type="checkbox"/> Dirty <input type="checkbox"/>		
Weather Condition: <input type="checkbox"/> Rainy <input checked="" type="checkbox"/> Dry <input type="checkbox"/>		
Inspection Time: <input checked="" type="checkbox"/> Day <input type="checkbox"/> Night <input type="checkbox"/>		
Evidence or breach of Code of Conduct can be observed: Yes/No		
Comply with Nisate Policy: Yes/No		
All Damages/ Pinned metal detacher: Yes/No With record Yes/No		
Recommendation on correction:		
OVER ALL RESULT: <b>(PASS)</b>		
Inspector's Signature: 	OK TO SHIP OUT	If Re-inspection Required, When: <b>NR</b>
Inspector's Name: <b>BAPPY</b>		Representative of Buying House:



**ICL FASHION**  
**FINAL INSPECTION**  
 House-79, Road-16, Block-A  
 Banani, Dhaka-1212


Report No. ①  
 Date 20/05/18

Measurement Check						
All Measurement within tolerance			Yes/No	Garments wash item		Yes/No
Remark						
Quality Audit						
Single/Double Sampling	Sample Size		Major	Minor		
Inspection Level	AQL Applied	Acceptable		Major	Minor	
Defect Description	Comment/Position	Critical	Major	Minor		
REJECT			01 ✓			
CARE LABEL DAMAGE			03 ✓			
N/O PRICE STICKER			01 ✓			
BROKEN STITCH			02 ✓			
MAIN LABEL OPEN			02 ✓			
OK RIB SHADING			02	04		
BROKEN PRINT			01	03		
TWISTING			01	02 ✓		
PRINT SLANTED			01			
PART SHADING				03		
OIL MARK				02		
DARTY SPOT				03		
CROSS POINT UP/DOWN				04		
			Actual Faults	14	24	
			Acceptable	21	21	
Comments: <b>ATTN:- TO MR. SHAHIDUL / MAHABUB</b> <b>WE FOUND ABOVE PROBLEM. IF ANY PROBLEM</b> <b>FROM BUYER SIDE, THAT FULLY RESPONSIBLE</b> <b>BY FACTORY.</b>						
<b>OK TO SHIP OUT</b> <b>(PASS)</b>						

Lot Disposition: Release/ Hold.

If Re-inspection Required, When

Accepted by:  Factory Representative

 Representative of Buying House





# NAFISA INT'L TRADING (BD) LTD.

(100% Export-oriented Garments Buying House)

Plot # 08, Road # 1/A, Gulshan-1, Dhaka-1212, Bangladesh. Tel: +8802 9886536  
9884003, 9886530, 9887142. +88 09606333222 (Karing). Fax: +88 02 98811313  
E-mail: info@nafisabd.com, nafisabd@bdcom.com, web: www.nafisabd.com

19190

## FINAL INSPECTION REPORT

Buyer: \_\_\_\_\_ Supplier: \_\_\_\_\_ Date: \_\_\_\_\_  
 Article/style: \_\_\_\_\_ Order Qty: \_\_\_\_\_ Carton Qty: \_\_\_\_\_  
 Order No.: \_\_\_\_\_ Inspection qty: \_\_\_\_\_ Consr / Gsm/GG: \_\_\_\_\_  
 Description: \_\_\_\_\_ Fabrication: \_\_\_\_\_  
 Inspector Name: \_\_\_\_\_ Assortment: \_\_\_\_\_  
 Q.C Name: \_\_\_\_\_ Mode of Ship: \_\_\_\_\_

Accessories & others details:  
 Main Label  Sticker/Barcode  Inlay/photo card  Shipping Mark: front & back / Side  
 Size Label  Poly Indv / Blstr  Belly Band  Shipping Mark: Ok /not ok  
 Care Label  Poly Sticker  Button  Ctn Mas. x x cm  
 Tab Label  Lining  Zipper  GW. NW.  
 Hang Tag  Eyel / Stoper  Hanger  Qty/ per ctn  
 Price Tag  Tissue  Others

Lot Size	Normal Sample				Acceptable Quality Level													
	1	2	3	4	1.5			2.5			4.0			6.5				
51-90	5	13	29	0	0	1	0	1	1	0	1	2	1	2	3			
91-150	8	25	52	0	0	1	0	1	1	0	1	2	1	3	5			
151-250	13	32	66	0	1	2	1	2	3	1	3	5	2	5	7			
251-500	20	50	90	1	2	3	1	3	5	2	5	7	3	7	10			
501-1200	22	60	125	1	3	5	2	5	7	3	7	10	5	10	14			
1201-2200	30	125	200	2	5	7	3	7	10	5	10	14	7	14	21			

Note: ♣ Level-1 Norm ♣ Level-2 Reduced ♣ Level-3 Tightened

Ctn #	Colour	Pcs	Defect Details	Critical	Major	Minor
					01	00
					01	00
					01	00
					01	00
					00	07
Total						

Remarks: \_\_\_\_\_

Inspected By: \_\_\_\_\_

Original -OC, Yellow Copy -M/R, Green Copy -Vendor

Inspection Result:  
 Pass   
 Re-check   
 Hold   
 Rejected

Vendors Acknowledgement: \_\_\_\_\_